



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI LX
Colour	Red
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	235 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #17	2018-06-18 16:31
MOT test number	204296512478
Result	✗ Failed
DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Offside Front Position lamp not working (4.2.1 (a))	

MOT #16	2018-02-20 13:11
MOT test number	482873895967
Result	✗ Failed
Fail Nearside rear brake excessively fluctuating (3.7.B.3)	
Advice N/s/f tyre worn on outer	
Advice Supplementary Restraint System warning lamp does not illuminate (5.4.2)	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)	
Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Power steering fluid on min	
Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)	
Fail Fuel tank leaking (7.2.3)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)	

**MOT #15** 2017-03-02 11:38**MOT test number** 990939117028**Result** ✓ Passed**Advice** Nearside Front Inner Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #14** 2017-03-02 11:16**MOT test number** 161562163870**Result** ✗ Failed**Fail** Nearside Rear rear brake binding (3.7.B.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Inner Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #13** 2016-02-29 10:46**MOT test number** 243852556798**Result** ✓ Passed

**MOT #12** 2016-02-29 08:56**MOT test number** 273377822500**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Coolant low**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #11** 2015-03-03 12:50**MOT test number** 917862565007**Result** ✓ Passed**MOT #10** 2015-03-03 10:53**MOT test number** 959342765046**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #9** 2014-02-20 13:04**MOT test number** 186291154445**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #8** 2014-02-20 09:02**MOT test number** 917641954000**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2013-03-01 08:18**MOT test number** 975810063041**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2012-02-29 11:21**MOT test number** 779130162028**Result** ✓ Passed**MOT #5** 2012-02-29 08:26**MOT test number** 139040362477**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #4** 2011-03-03 08:51**MOT test number** 125122361456**Result** ✓ Passed



MOT #3	2010-03-04 10:10
MOT test number	504363560046
Result	✓ Passed
MOT #2	2009-03-03 14:48
MOT test number	444632569041
Result	✓ Passed
MOT #1	2009-03-03 14:48
MOT test number	212542569071
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-01
Last registration	2018-06-18
Complete history	See info



Registration #1	2006-03-01	7 mi
Registration #2	2009-03-03	18.136 mi
Registration #3	2010-03-04	23.247 mi
Registration #4	2011-03-03	31.266 mi
Registration #5	2012-02-29	38.602 mi
Registration #6	2012-02-29	38.602 mi
Registration #7	2013-03-01	45.006 mi
Registration #8	2014-02-20	50.606 mi
Registration #9	2014-02-20	50.606 mi
Registration #10	2015-03-01	55.006 mi
Registration #11	2016-03-01	55.006 mi
Registration #12	2017-03-01	55.006 mi
Registration #13	2018-03-01	55.006 mi
Registration #14	2019-03-01	55.006 mi
Registration #15	2020-03-01	55.006 mi
Registration #16	2021-03-01	55.006 mi
Registration #17	2022-03-01	55.006 mi
Registration #18	2023-03-01	55.006 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1146 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FA5H31854