



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK220 CDI ELEGANCE
Colour	Black
Year of manufacture	2008
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-06-01
Pictures	14
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2024-05-10
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	26
Total items failed	9

MOT #20 2023-05-11 10:57**MOT test number** 832081209960**Result** Passed**Next expiry date** 2024-05-10

- Advice** Offside Front Play in steering rack inner joint(s) knocking
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn close to limit 225/50/16 (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #19 2023-05-02 14:42**MOT test number** 761191304277**Result** Failed

- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect no pattern (4.1.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn close to limit 225/50/16 (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s) knocking

MOT #18 2022-05-03 14:24**MOT test number** 966298655303**Result** Passed

**MOT #17**

2022-04-28 06:32

MOT test number

924290508658

Result

✗ Failed

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16

2021-12-31 07:52

MOT test number

479962461727

Result

✓ Passed

Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15

2020-07-22 11:42

MOT test number

641520576507

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2019-06-29 08:04

MOT test number

928165959859

Result

✓ Passed

Advice

O/s/f coil spring corroded

**MOT #13** 2018-07-23 16:57**MOT test number** 880171669277**Result** ✓ Passed**MOT #12** 2018-02-21 13:05**MOT test number** 668485130474**Result** ✓ Passed**MOT #11** 2018-02-19 16:44**MOT test number** 379108172123**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm attachment bracket modified and seriously weakened (2.4.A.2)**MOT #10** 2018-01-29 16:34**MOT test number** 107214797866**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #9** 2017-01-27 14:44**MOT test number** 161044984159**Result** ✓ Passed**Advice** Unable to check under side of vehicle fully due to lower panels fitted**MOT #8** 2017-01-26 09:54**MOT test number** 348565922075**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Unable to check under side of vehicle fully due to lower panels fitted**Advice** Nearside Rear Tyre worn close to the legal limit very low and worn on inner edge (4.1.E.1)

**MOT #7**

2016-01-25 15:06

MOT test number

278348918044

Result

✓ Passed

Advice Offside Front Steering system has slight free play detected at steering wheel steering rack tie bar inner joint (2.2.A.1b)

Advice Offside Front Tyre worn close to the legal limit worn badly on inner edge and worn on outer edge (4.1.E.1)

Advice N/s front tyre worn on edges

MOT #6

2016-01-25 09:47

MOT test number

608034937310

Result

✗ Failed

Advice N/s front tyre worn on edges

Advice Offside Front Tyre worn close to the legal limit worn badly on inner edge and worn on outer edge (4.1.E.1)

Fail Offside Lower Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt rear arm (2.4.G.2)

Advice Offside Front Steering system has slight free play detected at steering wheel steering rack tie bar inner joint (2.2.A.1b)

MOT #5

2015-02-04 10:37

MOT test number

839065535080

Result

✓ Passed

MOT #4

2014-01-29 16:49

MOT test number

658579624086

Result

✓ Passed

MOT #3

2014-01-29 16:49

MOT test number

836169024047

Result

✗ Failed

Pass with rectification Offside Headlamp aim too high (1.8)

Pass with rectification Nearside Headlamp aim too high (1.8)



MOT #2	2013-01-28 16:35
MOT test number	869268123038
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-01-30 14:28
MOT test number	479850732083
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 May 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	10 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-12-30
Last registration	2023-05-11
Complete history	See info



Registration #1	2008-12-30	19 mi
Registration #2	2012-01-30	37.212 mi
Registration #3	2013-01-28	49.578 mi
Registration #4	2014-01-29	59.039 mi
Registration #5	2015-02-04	64.966 mi
Registration #6	2016-01-25	73.843 mi
Registration #7	2016-01-25	73.843 mi
Registration #8	2017-01-26	79.088 mi
Registration #9	2017-01-27	79.089 mi
Registration #10	2018-01-29	82.845 mi
Registration #11	2018-02-19	82.850 mi
Registration #12	2019-05-20	91.277 mi
Registration #13	2019-05-20	91.277 mi
Registration #14	2019-05-20	91.277 mi
Registration #15	2019-05-20	91.277 mi
Registration #16	2019-05-20	91.277 mi
Registration #17	2019-05-20	91.277 mi
Registration #18	2019-05-20	91.277 mi
Registration #19	2019-05-20	91.277 mi
Registration #20	2019-05-20	91.277 mi
Registration #21	2019-05-20	91.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630638473