



report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I ROADSTER SE
Colour	Blue
Year of manufacture	2009
Top speed	135 mph
0 - 60 mph	7.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	188 Nm at 5.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2



Date	2021-06-23
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-10
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-28
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #15	2023-07-12 10:03
MOT test number	944135270313
Result	✓ Passed
Next expiry date	2024-07-28
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Service brake binding but not excessively n/s o/s (1.2.1 (f))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-07-21 13:28
MOT test number	966276816146
Result	✓ Passed

MOT #13	2021-07-29 14:39
MOT test number	460882937904
Result	✓ Passed

MOT #12	2020-07-10 08:11
MOT test number	662341555584
Result	✓ Passed
Advice	Anti-roll bar pin or bush worn but not resulting in excessive movement both front D bush (5.3.4 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11** 2019-07-08 11:52**MOT test number** 550108359606**Result** ✓ Passed**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Under trays fitted**MOT #10** 2019-07-08 10:31**MOT test number** 700840101892**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Under trays fitted**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MOT #9** 2018-07-13 09:43**MOT test number** 212933480071**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**MOT #8** 2017-07-07 09:03**MOT test number** 607572345261**Result** ✓ Passed**MOT #7** 2016-07-13 08:28**MOT test number** 895651820361**Result** ✓ Passed

**MOT #6** 2015-09-25 14:57**MOT test number** 325753415342**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-09-27 09:24**MOT test number** 997230874221**Result** ✓ Passed**MOT #4** 2013-12-19 15:00**MOT test number** 855113053353**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2013-12-19 09:46**MOT test number** 429413453430**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2012-12-07 11:38
MOT test number	609852942373
Result	✓ Passed

MOT #1	2012-12-07 11:38
MOT test number	718772342366
Result	✗ Failed

Pass with rectification

 Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:  
31 October 2023

✓

MOT

Expires:  
28 July 2024

Tax status	Expired at 31 October 2023
Days left	180 days too late
MOT expiry date	28 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-27
Last registration	2023-07-12
Complete history	<a href="#">See info</a>



Registration #1	2009-11-27	28 mi
Registration #2	2012-12-07	37.677 mi
Registration #3	2013-12-19	56.160 mi
Registration #4	2013-12-19	56.160 mi
Registration #5	2014-09-27	64.125 mi
Registration #6	2015-09-25	76.604 mi
Registration #7	2016-07-13	77.641 mi
Registration #8	2017-07-07	82.862 mi
Registration #9	2018-07-13	88.392 mi
Registration #10	2019-06-20	95.277 mi
Registration #11	2019-06-20	95.277 mi
Registration #12	2019-06-20	95.277 mi
Registration #13	2019-06-20	95.277 mi
Registration #14	2019-06-20	95.277 mi
Registration #15	2019-06-20	95.277 mi
Registration #16	2019-06-20	95.277 mi
Registration #17	2019-06-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1165 kg
Max. allowed weight	1375 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 10815650