



AGZ5340

report date: 2024-03-28

General information

Make	BMW
Model	3 SERIES 335D XDRIVE M SPORT
Colour	Grey
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-28
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT expiry date	2024-06-26
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	21
Total items failed	0

MOT #7	2023-06-27 14:33
MOT test number	174390942056
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre

MOT #6	2022-06-17 13:19
MOT test number	329260929660
Result	✓ Passed
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5**

2022-06-15 10:48

**MOT test number**

875270451607

**Result****✗ Failed**

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn front arm inner bush. (5.3.4 (a) (i))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn front arm inner bush. (5.3.4 (a) (i))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #4**

2022-06-14 12:38

**MOT test number**

947602279075

**Result****✗ Failed**

- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn Front arm inner bush. (5.3.4 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge Nearside & Offside Tyres wearing slightly on the inner edge. (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn Front arm inner bush. (5.3.4 (a) (i))

**MOT #3**

2021-06-19 15:44

**MOT test number**

298208470994

**Result****✓ Passed**



MOT #2	2019-07-05 16:59
MOT test number	571307571611
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge run flat 255/35/19 (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge run flat 225/40/19 (5.2.3 (e))

MOT #1	2019-07-05 15:11
MOT test number	607725563805
Result	✗ Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge run flat 225/40/19 (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge run flat 255/35/19 (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
26 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	26 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-12-22
Last registration	2023-06-27
Complete history	<a href="#">See info</a>



Registration #1	2015-12-22	8 mi
Registration #2	2019-07-05	63.101 mi
Registration #3	2019-07-05	63.100 mi
Registration #4	2019-07-05	63.100 mi
Registration #5	2021-06-19	80.486 mi
Registration #6	2019-07-05	63.100 mi
Registration #7	2019-07-05	63.100 mi
Registration #8	2019-07-05	63.100 mi
Registration #9	2019-07-05	63.100 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1811 mm
Height	1434 mm
Length	4633 mm
Wheel base	2810 mm
Kerb weight	1630 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	66959387