





report date: 2024-03-28

### General information

Make	BMW
Model	316 316D ES
Colour	Black
Year of manufacture	2010
Top speed	126 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/13




## Internet history

### Entry 1

Date 2021-08-28

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2023-09-26
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	25
Total items failed	12

MOT #13	2022-09-27 11:15
MOT test number	122862931736
Result	<b>✓</b> Passed
Next expiry date	2023-09-26
Advice Offside rear seat belt clip broken	
Advice Various body damage	
Advice Front number plate damaged	

MOT #12	2022-09-27 10:35
MOT test number	244400686541
Result	<b>×</b> Failed
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Front number plate damaged	
Advice Offside rear seat belt clip broken	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Various body damage	

MOT #11	2020-10-12 11:04
MOT test number	703377692624
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



MOT #10 2019-02-18 09:33

**MOT test number** 766209988173

**Result** ✓ Passed

MOT #9 2019-02-15 17:27

**MOT test number** 237233227162

Result X Failed

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Fail Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #8 2018-02-16 16:28

**MOT test number** 243005218650

**Result** ✓ Passed

**MOT #7** 2018-02-15 15:54

MOT test number 654796698389

Result X Failed

**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Rear Brakes imbalanced across an axle (3.7.B.5b)

**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)

MOT #6 2016-12-09 11:28

MOT test number 604420995575

**Advice** Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**Advice** Damage to nearside front of bumper

CarCheck.co.uk page 4/13



MOT #5 2016-12-08 17:07

**MOT test number** 228720668500

Result X Failed

Fail Offside Headlamp aim too high (1.8)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Damage to nearside front of bumper

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4 2015-11-27 12:45

**MOT test number** 478462293786

Result \rightarrow Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear brake pads slightly deteriorated

MOT #3 2014-11-20 16:26

MOT test number 988764724306

Result 

Passed

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Nearside rear tyre worn low on centre tread

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/13



YK10UKR

report date: 2024-03-28

MOT #2		2013-11-13 12:26
MOT test	number	305367613369
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1		2013-04-04 15:26
MOT test	number	529484393065
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front brake discs lipped/worn	
Notice	Under-trays fitted obscuring some underside components	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Rear brake discs lipped/worn	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/13



#### Tax & MOT check



X MOT

Tax expired: 7 June 2023

Expired: 26 September 2023

Tax status	Expired at 7 June 2023
Days left	326 days too late
MOT expiry date	26 September 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-10
Last registration	2022-09-27
Complete history	See info



Registration #1	2010-03-10	26 mi
Registration #2	2013-04-04	71.715 mi
Registration #3	2013-11-13	82.666 mi
Registration #4	2014-11-20	88.870 mi
Registration #5	2015-11-27	95.028 mi
Registration #6	2016-12-08	103.925 mi
Registration #7	2016-12-09	103.929 mi
Registration #8	2018-02-15	110.196 mi
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.777 es

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1811 mm
Height	1441 mm
Length	4624 mm
Wheel base	2810 mm
Kerb weight	1400 kg
Max. allowed weight	1920 kg

## Additional information

Fuel tank capacity	57 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles2Engine number85817394