





### General information

Make	ΤΟΥΟΤΑ
Model	AVENSIS D-4D TR
Colour	Blue
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	E







### Internet history


Entry 3	
Date	2
Pictures	8

2022-01-18

8

Listing price

View report



source: autotrader.co.uk

Entry 2	
Date	2021-07-15
Pictures	6
Listing price	View report



source: cargurus.co.uk

# Entry 1Date2021-07-14Pictures6Listing priceView report



CarCheck.co.uk



# MOT history

MOT expiry date	2024-12-29
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	11
Total items failed	4

MOT #12	2023-12-27 10:28
MOT test number	567162324206
Result	✓ Passed
Next expiry date	2024-12-29
Advice Front Tyre worn close to legal limit/worn on edge both (5	5.2.3 (e))
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11	2022-12-30 14:15
MOT test number	239732325273
Result	✓ Passed
<b>Minor</b> Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
<b>Minor</b> Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5	.3.4 (b) (i))





MOT #10	2022-12-30 13:04
MOT test number	605418491530
Result	🗙 Failed
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, ingress of dirt (2.1.3 (g) (i))	but preventing the
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5	i.3.4 (b) (i))
<b>Fail</b> Driver's view of the road through the swept area of the windscreen significantl obstruction (3.1 (a) (ii))	y affected by an
FailOffside Front Position lamp not working (4.2.1 (a) (ii))	
<b>Minor</b> Offside Front Track rod end ball joint dust cover damaged or deteriorated, be ingress of dirt (2.1.3 (g) (i))	ut preventing the
<b>Fail</b> Registration plate lamp inoperative in the case of a single lamp or all lamps (4	.7.1 (b) (ii))
<b>Fail</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))	
МОТ #9	2021-11-01 17:13
MOT test number	923572088323
Result	✓ Passed

МОТ #8	2021-02-05 11:03
MOT test number	446337890660
Result	✓ Passed

MOT #7	2020-02-10 11:42
MOT test number	647775954578
Result	✓ Passed

MOT #6	2019-02-04 11:43
MOT test number	847663345932
Result	🗸 Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	





MOT #5	2018-02-13 10:08
MOT test number	526453530988
Result	✓ Passed
MOT #4	2017-02-10 11:44
MOT test number	195214581020
Result	✓ Passed

MOT #3	2016-02-22 09:45
MOT test number	134358914969
Result	✓ Passed
Advice Undertrays fitted	

MOT #2	2015-02-09 14:25
MOT test number	387920345025
Result	✓ Passed
<b>Notice</b> Under-trays fitted obscuring some underside components	

MOT #1	2014-02-14 10:36
MOT test number	628265444007
Result	✓ Passed



Tax & MOT check

✓ Taxed	мот
Tax status	Expires: 29 December 2024 Valid until 1 July
Days left	62
MOT expiry date	29 December 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
*************	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plat	es.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2023-12-27
Complete history	See info



Registration #1	2011-03-01	7 mi
Registration #2	2014-02-14	28.621 mi
Registration #3	2015-02-09	37.741 mi
Registration #4	2016-02-22	45.911 mi
Registration #5	2017-02-10	53.644 mi
Registration #6	2018-02-13	61.071 mi
Registration #7	2019-02-04	68.388 mi
Registration #8	2020-02-10	76.576 mi
Registration #9		11.777 esi
-		
Registration #10		11.717 est
		11.517 es
Registration #10		01.000 est 01.000 est 01.000 est
Registration #10 Registration #11		01.000 est 01.000 est 01.000 est 01.000 est
Registration #10 Registration #11 Registration #12		0.000 es
Registration #10 Registration #11 Registration #12 Registration #13		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1810 mm
Height	1480 mm
Length	4765 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	2130 kg
Additional information	
Fuel tank capacity	60
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1AD5603868