





report date: 2024-03-28

General information

Make	ТОУОТА
Model	COROLLA VVTI T2
Colour	Silver
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.7 mpg
CO2 emission	190 g/km
CO2 label	J



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date	2022-12-12
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-06-05	
Pictures	10	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-24
MOT pass rate	100 %
MOT passed	17
Failed MOT tests	0
Total advice items	23
Total items failed	0

MOT #17		2023-06-02 07:22
MOT test	number	180509500949
Result		✓ Passed
Next expi	ry date	2024-06-24
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Brake pipe corroded, covered in grease or other material some (1.1.11 (c))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #16	2022-06-24 10:52
MOT test number	331079186374
Result	✓ Passed
MOT #15	2021-06-25 14:23
MOT test number	319759531937
Result	✓ Passed

MOT #14	2020-07-14 08:44
MOT test number	279757597804
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #13 2019-07-10 11:04

MOT test number 557722329790

Result ✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12 2018-07-10 07:41

MOT test number 264757582578

Result \(\sqrt{Passed} \)

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Exhaust noisy (8.1.1 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Advice Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 4/13



MOT #11 2017-07-10 13:05

MOT test number 635076754678

MOT #10 2016-07-11 12:01

MOT test number 392787209887

Advice BOTH FRONT TYRES WEARING LOW ON TREAD INNER AND OUTER EDGES 195/60/15

MOT #9 2015-07-10 12:47

MOT test number 209561195488

Notice Both front tyres slightly cracking on shoulders 195/60/15

MOT #8 2014-07-10 10:11

MOT test number 249191894492

Result
✓ Passed

MOT #7 2013-07-10 10:57

MOT test number 237221293429

Result \(\sqrt{Passed} \)

MOT #6 2012-07-10 15:56

MOT test number 978502392148

MOT #5 2011-07-12 15:32

MOT test number 625313391164

CarCheck.co.uk page 5/13



MOT #4	2010-07-13 14:54
MOT test number	334634890138
Result	✓ Passed
MOT #3	2009-07-15 16:29
MOT test number	751446499157
Result	✓ Passed
MOT #2	2008-07-16 16:31
MOT test number	494838398147
Result	✓ Passed
MOT #1	2007-07-18 15:10
MOT test number	951109397194
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITEL	HISLULY

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r		TA
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-07-29
Last registration	2023-06-02
Complete history	See info



Registration #1	2004-07-29	6 mi
Registration #2	2007-07-18	5.034 mi
Registration #3	2008-07-16	7.975 mi
Registration #4	2009-07-15	11.184 mi
Registration #5	2010-07-13	13.637 mi
Registration #6	2011-07-12	16.485 mi
Registration #7	2012-07-10	18.997 mi
Registration #8	2013-07-10	21.227 mi
Registration #9	2014-07-10	22.794 mi
Registration #10	2015-07-10	24.540 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		91.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	3ZZU464952 page 13/13