



General information

Make	VOLKSWAGEN
Model	FOX
Colour	Blue
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-02
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #15	2023-07-05 09:15
MOT test number	625383584215
Result	✓ Passed
Next expiry date	2024-07-16

MOT #14	2022-06-29 11:30
MOT test number	411483389966
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13	2021-07-17 08:54
MOT test number	959348153984
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #12**

2021-07-16 12:02

MOT test number

174075417068

Result

✗ Failed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Windscreen wiper blade defective (3.4 (b) (i))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #11**

2020-11-05 13:05

MOT test number

304553855354

Result

✓ Passed

Advice Offside Front tyre wearing on inner edge getting near the limit**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear silencer outer skin corroding**MOT #10**

2019-11-01 08:55

MOT test number

658017360309

Result

✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front tyer slight worn inner**Advice** Nearside Front Drag link end slightly misaligned rubber splitting (2.1.3 (e))

**MOT #9** 2019-10-31 15:24**MOT test number** 837442256867**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover missing split (5.3.4 (b) (ii))**Advice** Nearside Front Drag link end slightly misaligned rubber splitting (2.1.3 (e))**Pass with rectification** Offside Headlamp aim too far to the left (4.1.2 (a))**Advice** Offside Front tyer slight worn inner**MOT #8** 2018-10-16 09:51**MOT test number** 912239810935**Result** ✓ Passed**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement n/s and o/s (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2018-10-10 10:08**MOT test number** 306696254591**Result** ✗ Failed**Fail** Brake servo defective or ineffective vacuum hose cracked and split (1.1.10 (a) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement n/s and o/s (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2017-11-03 12:54**MOT test number** 451005025350**Result** ✓ Passed



MOT #5	2017-03-14 11:21
---------------	------------------

MOT test number	968818283674
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-03-23 13:05
---------------	------------------

MOT test number	618052501576
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
---------------	---

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

MOT #3	2015-03-26 09:10
---------------	------------------

MOT test number	659085785029
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-03-25 13:30
---------------	------------------

MOT test number	677724184020
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-03-25 10:27
---------------	------------------

MOT test number	536964583094
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
16 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2023-07-05
Complete history	See info



Registration #1	2010-03-31	28 mi
Registration #2	2013-03-25	17.366 mi
Registration #3	2014-03-25	26.063 mi
Registration #4	2015-03-26	32.492 mi
Registration #5	2016-03-23	37.768 mi
Registration #6	2017-03-14	43.340 mi
Registration #7	2017-11-03	47.433 mi
Registration #8	2018-10-10	53.602 mi
Registration #9	2018-10-16	53.602 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi
Registration #17	2019-05-29	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721