



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE AWD
Colour	Silver
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-20
Pictures	4
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-01
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #13	2024-01-02 10:12
MOT test number	820118317678
Result	✓ Passed
Next expiry date	2025-01-01
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2024-01-02 10:12
MOT test number	773206524989
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2022-12-20 08:45
MOT test number	803848671045
Result	✓ Passed

MOT #10	2021-09-10 16:08
MOT test number	292740659884
Result	✓ Passed

**MOT #9** 2020-12-24 12:20**MOT test number** 214068771701**Result** ✓ Passed**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge smooth (5.2.3 (e))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-12-23 14:09**MOT test number** 778033239569**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge smooth (5.2.3 (e))**MOT #7** 2019-12-20 11:47**MOT test number** 371834219785**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-09-19 11:37**MOT test number** 177823518990**Result** ✓ Passed

**MOT #5** 2017-10-12 15:17**MOT test number** 906136744000**Result** ✓ Passed**MOT #4** 2017-10-12 13:28**MOT test number** 370583322230**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2016-10-10 11:57**MOT test number** 288694103605**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2015-10-09 12:58**MOT test number** 350210960231**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine temp not taken no dipstick**MOT #1** 2014-09-29 11:55**MOT test number** 395582174446**Result** ✓ Passed**Notice** N/s front tyre cut in outer sidewall



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
1 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	1 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-27
Last registration	2024-01-02
Complete history	<a href="#">See info</a>



Registration #1	2011-09-27	10 mi
Registration #2	2014-09-29	35.294 mi
Registration #3	2015-10-09	42.504 mi
Registration #4	2016-10-10	49.187 mi
Registration #5	2017-10-12	53.832 mi
Registration #6	2017-10-12	53.834 mi
Registration #7	2018-09-19	57.226 mi
Registration #8	2019-12-20	68.598 mi
Registration #9	2020-01-01	68.598 mi
Registration #10	2020-01-01	68.598 mi
Registration #11	2020-01-01	68.598 mi
Registration #12	2020-01-01	68.598 mi
Registration #13	2020-01-01	68.598 mi
Registration #14	2020-01-01	68.598 mi
Registration #15	2020-01-01	68.598 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1883 kg
Max. allowed weight	2400 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

1047987