





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	207 SPORTIUM
Colour	Blue
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28

# Internet history

### Entry 3

Date 2023-05-08

Pictures 0

Listing price <u>View report</u>

### source: carcraft.co.uk

### Entry 2

Date 2023-04-30

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-19

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

# MOT history

MOT expiry date	2025-04-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	38
Total items failed	3

MOT #16		2024-04-19 09:42
MOT test	number	170915920141
Result		✓ Passed
Next exp	ry date	2025-04-25
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #15	2023-04-26 12:33
MOT test number	370761708263
Result	<b>✓</b> Passed
Advice Tiny chip on windscreen	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #14 2023-04-05 12:23 **MOT test number** 211821833867 Result ✓ Passed **Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Exhaust mounting defective 2 exhaust brackets broken exhaust still secure (6.1.2 (a)) Advice Advice Nearside Play in steering rack inner joint(s) Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Rear Side repeater slightly discoloured both (4.4.3 (a))

MOT #13		2023-04-03 14:19
MOT test	number	606041116991
Result		<b>×</b> Failed
MAJOR	Offside Headlamp aim too high (4.1.2 (a))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
MAJOR	Nearside Side repeater not working (4.4.1 (a) (ii))	
MAJOR	Nearside Front Lower Suspension component ball joint excessively worn (5.3.4	(a) (i))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Nearside Headlamp aim too high (4.1.2 (a))	
Advice	Exhaust mounting defective 2 exhaust brackets broken exhaust still secure (6.	1.2 (a))
MAJOR	Windscreen washer not working (3.5 (a))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Side repeater slightly discoloured both (4.4.3 (a))	
Advice	Nearside Play in steering rack inner joint(s)	
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 4/14



report date: 2024-03-28

 MOT #12
 2022-03-29 13:18

 MOT test number
 429793524056

 Result
 ✓ Passed

MOT #11 2021-03-06 10:11

**MOT test number** 939459332397

**Result** ✓ Passed

**MOT #10** 2021-03-06 10:11

**MOT test number** 478102586487

**Result** X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #9 2020-03-30 09:22

**MOT test number** 529693634690

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-03-12 15:48

MOT test number 732817202608

Result \( \sqrt{Passed} \)

Advice Rear Exhaust mounting defective exhaust still supported (6.1.2 (a))

**Advice** Bonnet pull broken but can still be opended

CarCheck.co.uk page 5/14



report date: 2024-03-28

**MOT #7** 2019-03-12 10:38 **MOT** test number 123786594759 Result × Failed **Advice** Rear Exhaust mounting defective exhaust still supported (6.1.2 (a)) Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) **MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Advice Bonnet pull broken but can still be opended Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **MAJOR** Advice Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) **MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #6	2018-03-28 12:53
MOT test number	874914241170
Result	✓ Passed

MOT #5 2018-03-28 10:15
MOT test number 171036121015

Result × Failed

Advice Coolant level below min

Windscreen washer provides insufficient washer liquid (8.2.3)

Fail

 MOT #4
 2017-03-27 09:16

 MOT test number
 763302780819

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28



MOT #2

MOT test number

513221360898

Result

Advice Exhaust bracket broken

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Front brake discs wearing on inner face

MOT #1	2015-03-30 10:14
MOT test number	178929185411
Result	<b>✓</b> Passed
Notice Front brake discs wearing on inner face	

CarCheck.co.uk page 7/14



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



faste since

FG12UPP

report date: 2024-03-28

# For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

More info >



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-03-30
Last registration	2024-04-19
Complete history	See info



Registration #1	2012-03-30	21 mi
Registration #2	2015-03-30	15.154 mi
Registration #3	2016-03-30	16.756 mi
Registration #4	2016-03-30	16.756 mi
Registration #5	2017-03-27	18.079 mi
Registration #6	2018-03-28	25.331 mi
Registration #7	2018-03-28	25.331 mi
Registration #8	2019-03-12	37.777 mi
Registration #9	2019-03-12	37.777 mi
Registration #10	2020-03-30	49.954 mi
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1219 kg
Max. allowed weight	1626 kg

# Additional information

Fuel tank capacity	50 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 page	14/14

Number of axles 2

**Engine number** FGAS1441366