





report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Black
Year of manufacture	2006
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	М



CarCheck.co.uk page 1/13



VO06GXR report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-08

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$			
10.71	α	h	sto	rv
101	() I		510	II V
	•		-	. ,

MOT expiry date	2025-03-31
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	16
Total items failed	1

MOT #19	2024-03-27 08:07
MOT test number	900260162514
Result	✓ Passed
Next expiry date	2025-03-31
Advice Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #18	2023-03-24 08:42
MOT test number	845660139785
Result	✓ Passed

MOT #17	2022-04-01 13:40
MOT test number	792194850593
Result	✓ Passed

MOT #16	2021-03-17 10:22

MOT test number 527612768525

Result

Passed

Advice Rear Offside Rear lower arm rose bush boots deteriorated

Advice Rear Rear Suspension arm ball joint dust cover severely deteriorated Both rear track control arm ball joints boots deteriorated

Advice Rear Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs slightly corroded on inner face

Advice Rear Anti-roll bar linkage ball joint dust cover severely deteriorated Both rear

CarCheck.co.uk page 3/13



MOT #15

VO06GXR

report date: 2024-03-29

2020-01-23 07:51

MOT test number 850554521302

Result ✓ Passed

Advice Offside Rear lower arm rose bush boots deteriorated

Minor Rear Suspension arm ball joint dust cover severely deteriorated Both rear track control arm ball joints boots deteriorated (5.3.4 (b) (i))

Minor Anti-roll bar linkage ball joint dust cover severely deteriorated Both rear (5.3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs slightly corroded on inner face (1.1.14 (a) (ii))

MOT #14 2020-01-17 12:29

MOT test number 947711505821

Result X Failed

MAJOR Nearside Rear Lower Suspension arm pin or bush excessively worn rear rose bush (5.3.4 (a) (i))

Minor Rear Suspension arm ball joint dust cover severely deteriorated Both rear track control arm ball joints boots deteriorated (5.3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs slightly corroded on inner face (1.1.14 (a) (ii))

MAJOR Direction indicator incorrect colour white (4.4.3 (a))

Advice Oil leak, but not excessive small oil leak from rear diff (8.4.1 (a) (i))

Minor Anti-roll bar linkage ball joint dust cover severely deteriorated Both rear (5.3.4 (b) (i))

Advice Offside Rear lower arm rose bush boots deteriorated

MOT #13 2019-01-11 10:15

MOT test number 809586778507

Result

Passed

MOT #12 2018-01-09 09:11

MOT test number 991060282469

Result

Passed

CarCheck.co.uk page 4/13



Result

VO06GXR

report date: 2024-03-29

✓ Passed

MOT #11		2018-01-09 09:11
MOT test number		728100293587
Result		X Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
MOT #10		2017-01-09 09:17
MOT test number		608654488937
Result		✓ Passed
MOT #9		2016-01-04 09:50
MOT test number		912364185360
Result		✓ Passed
MOT #8		2015-01-06 09:07
MOT test number		166556005086
Result		✓ Passed
MOT #7		2013-12-20 12:10
MOT test number		815964053340
Result		✓ Passed
		2012 01 10 00 22
MOT #6		2013-01-10 09:32
MOT test number		228190713052
Result		✓ Passed
MOT #F		2012 01 00 12-52
MOT took number		2012-01-09 12:53
MOT test number		379939102014

CarCheck.co.uk page 5/13



VO06GXR report date: 2024-03-29

MOT #4 2011-01-20 12:01
MOT test number 396440121079

Result \rightarrow Passed

MOT #3 2010-07-19 14:26

MOT test number 330540400209

Result ✓ Passed

MOT #2 2009-08-14 13:02

MOT test number 312906329441

Result ✓ Passed

MOT #1 2009-04-28 11:19

MOT test number 680038819140

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



VOO6GXR report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



furthe scinors

VO06GXR

report date: 2024-03-29

More info >

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this JAGUAR had different number plates.

CarCheck.co.uk page 10/13



VOO6GXR report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-04-20
Last registration	2024-03-27
Complete history	See info



Registration #1	2006-04-20	8 mi
Registration #2	2009-04-28	148 mi
Registration #3	2009-08-14	267 mi
Registration #4	2010-07-19	6.288 mi
Registration #5	2011-01-20	11.183 mi
Registration #6	2012-01-09	17.772 mi
Registration #7	2013-01-10	21.285 mi
Registration #8	2013-12-20	24.981 mi
Registration #9	2015-01-06	28.510 mi
Registration #10	2016-01-04	30.281 mi
Registration #11	2017-01-09	33.100 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		11,777 66

More info >

CarCheck.co.uk page 12/13



VOO6GXR report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	542328359FG

CarCheck.co.uk page 13/13