





report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 COUPE HDI GT
Colour	Grey
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	440 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	33.2 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-22
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	24
Total items failed	15

MOT #24		2023-12-23 16:31
MOT test	number	395048872242
Result		✓ Passed
Next expi	ry date	2024-12-22
Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both si	des (1.1.14 (a) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Coil spring worn (5.3.1 (b) (i))	

MOT #23		2023-12-23 16:31
MOT test	number	796193105487
Result		× Failed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Coil spring worn (5.3.1 (b) (i))	
Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))		
Pass wit	h rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT #22 2022-12-15 16:22

MOT test number 124274718107

MOT #21 2022-12-12 14:39

MOT test number 529995643404

Result × Failed

Fail Offside Front Outer Brake pad(s) incorrectly mounted (1.1.13 (c))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #20 2021-12-08 15:47

MOT test number 346603789592

Result \rightarrow Passed

MOT #19 2020-12-03 14:32

MOT test number 503645628696

Result ✓ Passed

MOT #18 2019-10-21 09:41

MOT test number 860789086068

Minor Nearside Rear Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #17 2018-11-21 15:17

MOT test number 507311086881

CarCheck.co.uk page 3/14



Fail

KV56OSN

report date: 2024-03-28

MOT test number

868231664305

Result

Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

 MOT #15
 2017-10-07 09:40

 MOT test number
 463023216966

 Result
 ✓ Passed

 MOT #14
 2017-10-07 09:40

 MOT test number
 205215647093

 Result
 X Failed

 Pass with rectification
 Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #13	2016-09-28 15:09
MOT test number	469708863566
Result	✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12 2016-09-28 08:40 **MOT** test number 212679750012 Result × Failed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Front Front constant velocity joint is slightly worn (2.5.C.1b) **Advice** Brake pedal loose

MOT #11

MOT test number

637164003868

Result

Advice Oil leak

2015-10-26 14:15

Continuation of the properties of th

MOT #10

MOT test number

932059424602

Result

Advice Oil leak

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #9
 2014-10-27 11:10

 MOT test number
 967180504312

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8 2014-10-24 15:34 **MOT test number** 616037794256 Result **★** Failed Fail Nearside Lower Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a) Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Fail Front registration plate deteriorated (6.3.1d) Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Nail in nearside rear tyre

MOT #7	2013-10-25 10:55
MOT test number	988748993285
Result	✓ Passed
MOT #6	2013-10-25 09:48
MOT test number	336518093277
Result	X Failed
Fail Rear brake disc in such a condition that it is seriously weakened (3.5.1i)	

MOT #5	2012-10-12 16:58
MOT test number	619846382254
Result	✓ Passed
Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)	

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #4 2012-09-21 10:53

MOT test number 415895262299

Result X Failed

Advice Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Fail Power steering inoperative (2.3.3a)

MOT #3 2011-09-13 10:20

MOT test number 716996251266

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2010-09-21 10:07

MOT test number 360954560473

Result ✓ Passed

MOT #1 2009-09-21 09:09

MOT test number 663064969241

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



KV56OSN report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



KV56OSN report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Plate since

KV56OSN

More info >

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIN
	UK
Plate since	UK

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-09-26
Last registration	2023-12-23
Complete history	See info



Registration #1	2006-09-26	26 mi
Registration #2	2009-09-21	47.152 mi
Registration #3	2010-09-21	64.237 mi
Registration #4	2011-09-13	78.722 mi
Registration #5	2012-09-21	88.364 mi
Registration #6	2012-10-12	88.481 mi
Registration #7	2013-10-25	95.171 mi
Registration #8	2013-10-25	95.170 mi
Registration #9	2014-10-24	101.237 mi
Registration #10	2014-10-27	101.237 mi
Registration #11	2015-10-26	113.308 mi
Registration #12	2015-10-26	113.308 mi
Registration #13	2016-09-28	118.513 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		91.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		D.777 es
Registration #25		11.777 es




report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1868 mm
Height	1399 mm
Length	4815 mm
Wheel base	2725 mm
Kerb weight	1799 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 14

Number of axles 2

Engine number TRD10083409