



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Grey
Year of manufacture	2009
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	24
Total items failed	12

MOT #19	2023-09-29 07:54
MOT test number	608395197260
Result	✓ Passed
Next expiry date	2024-10-15
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18	2023-09-28 15:55
MOT test number	954876504587
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17	2023-09-20 13:53
MOT test number	720653332535
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Rear Seat belt not functioning as intended retracting/release keeps locking when trying to plug it in ,, takes a multitude of attempts to pull it out, (7.1.2 (c))
Advice	Exhaust has a minor leak of exhaust gases borderline pass, (6.1.2 (a))

**MOT #16** 2022-10-16 12:20**MOT test number** 329043989412**Result** ✓ Passed**MOT #15** 2022-10-11 13:50**MOT test number** 508334396131**Result** ✗ Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #14 2021-10-07 08:59**MOT test number** 485028513844**Result** ✓ Passed**MOT #13** 2021-10-06 14:47**MOT test number** 635178245528**Result** ✗ Failed

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2020-09-29 10:32**MOT test number** 986694879912**Result** ✓ Passed

Advice Exhaust has a minor leak of exhaust gases Downpipe joint (6.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

**MOT #11**

2020-09-29 08:22

MOT test number

459231637749

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases Downpipe joint (6.1.2 (a))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

MOT #10

2019-10-08 09:05

MOT test number

138562412860

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front tyre is worn on inner edge

MOT #9

2019-10-07 08:29

MOT test number

642100913310

Result**✗ Failed**

- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front tyre is worn on inner edge
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #8** 2018-09-05 10:48**MOT test number** 225382355612**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear tyre is slightly cracked & worn on inner edge**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2017-09-16 15:17**MOT test number** 982948188869**Result** ✓ Passed**MOT #6** 2016-09-24 15:14**MOT test number** 611165495288**Result** ✓ Passed**MOT #5** 2015-09-21 11:11**MOT test number** 725380248171**Result** ✓ Passed**MOT #4** 2014-09-26 15:53**MOT test number** 927239664235**Result** ✓ Passed**MOT #3** 2013-09-28 10:23**MOT test number** 146251373217**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2012-09-28 15:06
MOT test number	235222872203
Result	✓ Passed

MOT #1	2012-09-28 15:06
MOT test number	988812872254
Result	✗ Failed

Pass with rectification

 Offside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
15 October 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	EK59NXB
Plate since	2019-03-29
Current registration	EK59NXB
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-30
Last registration	2023-09-29
Complete history	See info



Registration #1	2009-09-30	14 mi
Registration #2	2012-09-28	31.817 mi
Registration #3	2013-09-28	44.000 mi
Registration #4	2014-09-26	53.582 mi
Registration #5	2015-09-21	64.805 mi
Registration #6	2016-09-24	76.808 mi
Registration #7	2017-09-16	87.475 mi
Registration #8	2018-09-05	100.609 mi
Registration #9	2019-10-07	115.654 mi
Registration #10	2019-10-08	115.654 mi
Registration #11	2019-10-08	115.654 mi
Registration #12	2019-10-08	115.654 mi
Registration #13	2019-10-08	115.654 mi
Registration #14	2019-10-08	115.654 mi
Registration #15	2019-10-08	115.654 mi
Registration #16	2019-10-08	115.654 mi
Registration #17	2019-10-08	115.654 mi
Registration #18	2019-10-08	115.654 mi
Registration #19	2019-10-08	115.654 mi
Registration #20	2019-10-08	115.654 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3421928