



RENAULT

VN05GNU

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27DCI 100 SWB P/V
Colour	Silver
Year of manufacture	-
Top speed	97 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	240 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2021-03-02 10:52
MOT test number	440368096774
Result	✓ Passed
Next expiry date	2022-03-01
Advice	Front Tyre worn close to legal limit/worn on edge 1.6 (5.2.3 (e))

MOT #13	2019-04-15 15:59
MOT test number	856150929674
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front Track rod end ball joint has slight play both (2.1.3 (b) (i))

**MOT #12**

2019-04-15 15:59

MOT test number

328007852326

Result

✗ Failed

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Front Track rod end ball joint has slight play both (2.1.3 (b) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Brake pedal wearing smooth (1.1.2 (c))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11**

2018-03-15 15:10

MOT test number

736314086161

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Track rod end ball joint has slight play (2.2.B.1f)**MOT #10**

2017-03-17 17:07

MOT test number

303902101221

Result

✓ Passed

**MOT #9** 2017-03-17 17:07**MOT test number** 164761132012**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Front Direction indicators not working (1.4.A.2c)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2014-05-31 13:30**MOT test number** 809551054144**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2013-06-01 14:43**MOT test number** 595852353122**Result** ✓ Passed**Notice** Oil leak around engine wet shock absorbers rear brake discs corroded and lipped**MOT #6** 2012-06-07 09:51**MOT test number** 319499752171**Result** ✓ Passed**Notice** Emitting blue smoke

**MOT #5** 2011-09-10 09:57**MOT test number** 798743351212**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-08-11 13:00**MOT test number** 644283020283**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-08-07 16:06**MOT test number** 121989419288**Result** ✓ Passed**Notice** Slight play in steering rack**Notice** Oil leak**Notice** Rear brake discs starting to rust/ wear**Notice** Check front inner brake pads**Notice** Nearside rear tyre tread wearing low on edges**Notice** Rear brake pads wearing low**MOT #2** 2009-04-17 09:22**MOT test number** 843427709136**Result** ✓ Passed**MOT #1** 2008-06-04 09:30**MOT test number** 221466858426**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2005-04-19
Last registration	2021-03-02
Complete history	See info



Registration #1	2005-04-19	29 mi
Registration #2	2008-06-04	103.862 mi
Registration #3	2009-04-17	28.238 mi
Registration #4	2009-08-07	28.288 mi
Registration #5	2010-08-11	35.711 mi
Registration #6	2011-09-10	66.257 mi
Registration #7	2012-06-07	67.568 mi
Registration #8	2013-06-01	82.967 mi
Registration #9	2014-06-01	95.277 mi
Registration #10	2015-06-01	103.862 mi
Registration #11	2016-06-01	111.238 mi
Registration #12	2017-06-01	118.238 mi
Registration #13	2018-06-01	125.238 mi
Registration #14	2019-06-01	132.238 mi
Registration #15	2021-03-02	139.238 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Length	4782 mm
Kerb weight	1677 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C414332