



report date: 2024-03-28

General information

Make	KIA
Model	MAGENTIS CRDI GS
Colour	Black
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN

**MOT history**

MOT #15	2019-11-22 16:28
MOT test number	396232095872
Result	✓ Passed
Next expiry date	2020-11-21
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2019-11-21 13:40
MOT test number	554738860859
Result	✗ Failed
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #13**

2018-10-24 14:14

MOT test number

408799507159

Result

✓ Passed

Advice

Both rear trail arm bushes worn

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2017-11-21 14:22

MOT test number

158253936910

Result

✓ Passed

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #11

2017-11-20 13:22

MOT test number

593280595868

Result

✗ Failed

Fail

Parking brake: efficiency below requirements (3.7.B.7)

Fail

Front front brake binding Both Front Wheels Binding (3.7.B.1)

Fail

Rear rear brake binding Both Rear Brakes Binding (3.7.B.1)

Fail

Nearside Front Direction indicator not working (1.4.A.2c)

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail

Rear rear brake excessively fluctuating (3.7.B.3)

Fail

Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail

Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

MOT #10

2016-10-11 16:14

MOT test number

826111875212

Result

✓ Passed

**MOT #9** 2016-10-11 14:04**MOT test number** 598627978030**Result** ✗ Failed**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Eye level brake light out**MOT #8** 2015-10-22 12:09**MOT test number** 601760415398**Result** ✓ Passed**Advice** Nearside Headlamp affected by the operation of another lamp nearside headlight unit faulty but moved wiring loom and was operating at time of test. may require further investigation if fault re-occurs (1.7.5c)**Advice** Anti-roll bar linkage has slight play in a ball joint both front (2.4.G.2)**MOT #7** 2014-10-20 10:58**MOT test number** 825813394221**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2013-11-04 12:54**MOT test number** 439478203369**Result** ✓ Passed**Advice** Nearside rear parking (secondary) brake grabbing slightly (3.7.B.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2012-09-04 09:38**MOT test number** 575658042259**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2011-09-22 16:44**MOT test number** 348705461264**Result** ✓ Passed**MOT #3** 2011-09-22 10:22**MOT test number** 337615561425**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre worn on both edges**Fail** Nearside Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre at 3mm tread depth and worn on inner edge**Notice** Nearside front tyre heavily worn on inner edge**Fail** Offside Headlamp aim too low (1.8)**MOT #2** 2010-07-02 11:25**MOT test number** 470023980102**Result** ✓ Passed



MOT #1	2010-06-29 15:08
MOT test number	524910180196
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Front brake disc in such a condition that it is seriously weakened (3.5.1i)



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-06-29
Last registration	2019-11-22
Complete history	See info



Registration #1	2007-06-29	18 mi
Registration #2	2010-06-29	40.340 mi
Registration #3	2010-07-02	40.394 mi
Registration #4	2011-09-22	55.787 mi
Registration #5	2011-09-22	55.787 mi
Registration #6	2012-09-04	68.663 mi
Registration #7	2013-11-04	76.452 mi
Registration #8	2014-10-20	79.522 mi
Registration #9	2015-05-20	85.277 mi
Registration #10	2015-05-20	85.277 mi
Registration #11	2015-05-20	85.277 mi
Registration #12	2015-05-20	85.277 mi
Registration #13	2015-05-20	85.277 mi
Registration #14	2015-05-20	85.277 mi
Registration #15	2015-05-20	85.277 mi
Registration #16	2019-11-22	85.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1805 mm
Height	1480 mm
Length	4735 mm
Wheel base	2720 mm
Kerb weight	1525 kg
Max. allowed weight	2045 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4EA6H20307