





General information

| Make | VAUXHALL |
|---------------------|----------------|
| Model | VIVARO |
| Colour | White |
| Year of manufacture | 2018 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP | 0 < 101 A |
|-------------------------|---------------------|-------------------------------------|
| Max. torque | 300 Nm at 1.750 rpm | 101 - 120 ^B _C |
| Engine capacity | 1.598 cc | 121 - 140 P |
| Cylinders | 4 | 141 - 165 F |
| Fuel type | Diesel | 166 - 185 H LABEL H |
| Consumption city | 36.2 mpg | 186 - 225 J |
| Consumption extra urban | 48.7 mpg | 225+ L |
| Consumption combined | 43.5 mpg | |
| CO2 emission | 170 g/km | |
| CO2 label | Н | |



Internet history

Entry 1

Date Pictures 2021-08-03

12

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-08-23 |
|--------------------|------------|
| MOT pass rate | 57 % |
| MOT passed | 4 |
| Failed MOT tests | 3 |
| Total advice items | 4 |
| Total items failed | 8 |

| MOT #7 | 2023-07-25 16:41 |
|------------------|------------------|
| MOT test number | 550243992623 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-23 |

| МОТ #6 | | 2023-07-24 11:34 |
|--------------------------|----------------------------------------------------------------|------------------|
| MOT test number | | 499656376672 |
| Result | | 🗙 Failed |
| Fail Reversing lamp inop | perative (4.6.1 (a)) | |
| Pass with rectification | Nearside Daytime running lamp not working 580 (4.2.1 (a) (ii)) | |

| MOT #5 | 2022-07-29 15:36 |
|-----------------|------------------|
| MOT test number | 513481929268 |
| Result | ✓ Passed |
| | |

| MOT #4 | 2022-07-28 15:36 |
|--------------------------------------------------------------------------------------|------------------|
| MOT test number | 743632145364 |
| Result | 🗙 Failed |
| Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | |





| MOT # | 3 | 2021-08-24 16:58 |
|---------------|---------------------------------------------------------------------------------------|------------------|
| MOT te | est number | 961443334935 |
| Result | | ✓ Passed |
| | | |
| MOT # | 2 | 2021-03-31 15:48 |
| MOT te | est number | 149421711615 |
| Result | | ✓ Passed |
| Advie | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii)) |
| Advie | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| | | |
| MOT # | 1 | 2021-03-31 07:53 |
| MOT te | est number | 508624057195 |
| Result | | 🗙 Failed |
| Fail | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail | Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | |
| Advie | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Fail | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |
| Fail (ii)) | Nearside Track rod end ball joint worn to the extent there is a serious risk of detac | hment (2.1.3 (b) |
| Advi | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii)) |



Tax & MOT check

Tax calculation

| Tax due: 1 March 2025 | ✓ axed | Expires: 23 August 2024 | ✓ МОТ |
|---------------------------------|-----------|-----------------------------------|-----------------------|
| Tax status | | | Valid until 1 March |
| Days left MOT expiry date | | | 305 23 August 2024 |
| Full MOT history | | | See MOT history |
| | | | |

Vehicle class 39 Standard rate (12 months) £ 320,00, Standard rate (6 months) £ 176,00,





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FE CO |
| Category | A RINPE |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPLI |
| Туре | W SCO |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|-----------------------------------------------------------------|-------------|
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| | |
| Plate since | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-03-29 |
| Last registration | 2023-07-25 |
| Complete history | See info |



| Registration #1 | 2018-03-29 | 17 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-03-31 | 72.564 mi |
| Registration #3 | 2021-03-31 | 72.565 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | 2021-08-24 | 77.688 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.177 esi |
| Registration #8 | | 11.117 esi |
| Registration #9 | | 11.777 esi |

More info >





Safety ratings

| NCAP rating | **** | Juna an |
|----------------|-----------------|---------|
| Adult | 52% | EURO |
| Children | 91% | |
| Pedestrian | 53% | |
| Safety systems | 57% | |
| Overall rating | 61% | |
| Video | see crash video | |



| Dimensions & weight | |
|------------------------|---------------------|
| Width | 2283 mm |
| Height | 1971 mm |
| Length | 4998 mm |
| Kerb weight | 1800 kg |
| Max. allowed weight | 2800 kg |
| Additional information | |
| Fuel tank capacity | 80 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | R9M H4 - C108731LWX |