




report date: 2024-03-29

## General information

Make	VOLVO
Model	XC70 D4 SE AWD
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I








Internet history

Entry 1

Date	2021-05-21
Pictures	27
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2025-04-04
<b>MOT pass rate</b>	70 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	21
<b>Total items failed</b>	2

<b>MOT #10</b>	2024-04-05 10:05
<b>MOT test number</b>	269552450686
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-04-04

<b>MOT #9</b>	2022-04-14 11:36
<b>MOT test number</b>	919490831738
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #8</b>	2022-04-13 13:27
<b>MOT test number</b>	907654793538
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2020-08-18 13:28**MOT test number** 653586073692**Result** ✓ Passed**Advice** Under tray fitted**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #6** 2020-08-18 08:50**MOT test number** 356101144845**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Under tray fitted**MOT #5** 2019-05-16 10:14**MOT test number** 970101309611**Result** ✓ Passed**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front bushes (5.3.4 (a) (i))**Advice** Undertray fitted**MOT #4** 2018-05-18 10:23**MOT test number** 285527634660**Result** ✓ Passed**Advice** Under tray fitted**MOT #3** 2017-05-22 08:47**MOT test number** 401222372957**Result** ✓ Passed



MOT #2	2016-05-16 10:25
MOT test number	784516216008
Result	✓ Passed
Advice	Engine covers restricts vision
Advice	Offside Front Inner Tyre worn close to the legal limit & outer edges (4.1.E.1)
Advice	Undertrays restricts vision
Advice	Nearside Front Inner Tyre worn close to the legal limit & outer edges (4.1.E.1)

MOT #1	2016-05-16 10:25
MOT test number	245890038898
Result	✗ Failed
Advice	Engine covers restricts vision
Advice	Offside Front Inner Tyre worn close to the legal limit & outer edges (4.1.E.1)
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)
Advice	Nearside Front Inner Tyre worn close to the legal limit & outer edges (4.1.E.1)
Advice	Undertrays restricts vision
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
4 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	4 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-30
Last registration	2024-04-05
Complete history	<a href="#">See info</a>



Registration #1	2013-05-30	13 mi
Registration #2	2016-05-16	30.474 mi
Registration #3	2016-05-16	30.474 mi
Registration #4	2017-05-22	37.591 mi
Registration #5	2018-05-18	49.513 mi
Registration #6	2019-05-16	61.253 mi
Registration #7	2020-05-20	75.277 mi
Registration #8	2021-05-20	91.277 mi
Registration #9	2022-05-20	109.277 mi
Registration #10	2023-05-20	129.277 mi
Registration #11	2024-04-05	151.277 mi
Registration #12	2024-04-05	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1851 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1277808