




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI CC DSG
Colour	Grey
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





**Internet history**

**Entry 1**

Date	2021-07-10
Pictures	2
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-03-24
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	24
Total items failed	7

<b>MOT #18</b>	2024-03-02 15:11
MOT test number	948879909856
Result	✓ Passed
Next expiry date	2025-03-24

<b>MOT #17</b>	2023-03-25 13:33
MOT test number	765549043793
Result	✓ Passed
<b>Advice</b>	Front Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement pan arm (5.3.4 (a) (i))

<b>MOT #16</b>	2022-05-12 07:28
MOT test number	458894817383
Result	✓ Passed

<b>MOT #15</b>	2021-07-30 13:33
MOT test number	955432713849
Result	✓ Passed



<b>MOT #14</b>	2021-07-14 10:27
<b>MOT test number</b>	504531332246
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #13</b>	2020-11-12 14:29
<b>MOT test number</b>	635278720626
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear all bushes have some wear
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge very badly warn (5.2.3 (e))
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Advice</b>	Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #12</b>	2020-11-12 09:44
<b>MOT test number</b>	822044875145
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Rear all bushes have some wear
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Fail</b>	Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge very badly warn (5.2.3 (e))
<b>Advice</b>	Nearside Rear Nail in tyre



<b>MOT #11</b>	2019-11-15 15:46
<b>MOT test number</b>	275981628341
<b>Result</b>	✓ Passed
<b>Advice</b>	Low flow diesel

<b>MOT #10</b>	2019-02-28 16:31
<b>MOT test number</b>	342027496281
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2019-02-28 10:33
<b>MOT test number</b>	901780272406
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

<b>MOT #8</b>	2018-02-26 14:01
<b>MOT test number</b>	987159013458
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2018-02-26 14:01
<b>MOT test number</b>	549007595994
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp not working on dipped beam (1.7.5a)

<b>MOT #6</b>	2017-03-03 15:14
<b>MOT test number</b>	856027694379
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #5 2017-03-02 17:37

MOT test number 430600028104

Result ✗ Failed

**Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp indicator affecting side light (1.1.A.3f)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #4 2016-02-18 15:56

MOT test number 395641640844

Result ✓ Passed

MOT #3 2015-02-13 12:20

MOT test number 995004545085

Result ✓ Passed

MOT #2 2014-03-03 13:44

MOT test number 639652364002

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2013-03-06 11:59

MOT test number 665545463064

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 May 2025

✓  
**MOT**

**Expires:**  
24 March 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	24 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>Y11111</b>
Plate since	2024-03-28
Current registration	<b>Y11111</b>
Plate since	2024-03-28

More info >



**Finance check**

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-03
Last registration	2024-03-02
Complete history	<a href="#">See info</a>



Registration #1	2010-03-03	16 mi
Registration #2	2013-03-06	27.243 mi
Registration #3	2014-03-03	38.476 mi
Registration #4	2015-02-13	47.711 mi
Registration #5	2016-02-18	57.429 mi
Registration #6	2017-03-02	64.416 mi
Registration #7	2017-03-03	64.418 mi
Registration #8	2018-02-26	70.409 mi
Registration #9	2018-02-26	70.409 mi
Registration #10	2019-02-28	77.034 mi
Registration #11	2019-03-02	80.377 mi
Registration #12	2019-03-02	80.377 mi
Registration #13	2019-03-02	80.377 mi
Registration #14	2019-03-02	80.377 mi
Registration #15	2019-03-02	80.377 mi
Registration #16	2019-03-02	80.377 mi
Registration #17	2019-03-02	80.377 mi
Registration #18	2019-03-02	80.377 mi
Registration #19	2019-03-02	80.377 mi
Registration #20	2019-03-02	80.377 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1491 kg
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

---

<b>Number of seats</b>	4
<b>Number of axles</b>	2
<b>Engine number</b>	CBB 328803