



HYI4GFX

report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ3
Colour	Black
Year of manufacture	2014
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-02-04
Pictures	2
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	10
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-02-14
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	6

MOT #11 2024-02-15 16:40

MOT test number 610984806536

Result ✓ Passed

Next expiry date 2025-02-14

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10 2024-02-05 15:48

MOT test number 613695627836

Result ✗ Failed

Fail Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))

Fail Brake pedal has insufficient reserve travel (1.1.2 (a))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9** 2023-02-06 17:38**MOT test number** 349081643875**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Front Windscreen wiper blade defective split (3.4 (b) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt nearside and offside**MOT #8** 2021-12-02 11:36**MOT test number** 229264586295**Result** ✓ Passed**MOT #7** 2020-11-26 16:48**MOT test number** 811149978457**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2020-01-23 12:04**MOT test number** 292483264480**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-01-11 15:37**MOT test number** 666750334192**Result** ✓ Passed

**MOT #4** 2019-01-11 10:28**MOT test number** 986346732611**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-01-15 11:26**MOT test number** 849928095602**Result** ✓ Passed**Advice** Both front tyres worn low**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2018-01-15 11:26**MOT test number** 658610849593**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Both front tyres worn low**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2017-01-19 16:30**MOT test number** 938856249420**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-04
Last registration	2024-02-15
Complete history	See info



Registration #1	2014-03-04	23 mi
Registration #2	2017-01-19	7.826 mi
Registration #3	2018-01-15	13.958 mi
Registration #4	2018-01-15	13.958 mi
Registration #5	2019-01-11	19.258 mi
Registration #6	2019-01-11	19.259 mi
Registration #7	2020-01-23	25.601 mi
Registration #8	2020-01-23	25.601 mi
Registration #9	2020-01-23	25.601 mi
Registration #10	2020-01-23	25.601 mi
Registration #11	2020-01-23	25.601 mi
Registration #12	2020-01-23	25.601 mi
Registration #13	2020-01-23	25.601 mi
Registration #14	2020-01-23	25.601 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	80%
Pedestrian	72%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1620 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1240 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	M16A-1820236