





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT S TDI BLUEMOTION TECHNOLOGY
Colour	Red
Year of manufacture	2014
Top speed	130 mph
0 - 100 km/h	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-07

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	3

MOT #10	2023-09-28 11:59
MOT test number	410557306245
Result	✓ Passed
Next expiry date	2024-10-02

MOT #9	2023-09-28 11:59
MOT test number	609249085203
Result	× Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOI#8		2022-10-03 09:28
MOT test	number	822407874211
Result		✓ Passed
MOT #7		2021-09-19 10:17
MOT test number 361485061893		
Result		✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or c	ords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2020-10-01 08:23

MOT test number 662307830494

Result Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-10-01 08:23

MOT test number 630881639404

Result X Failed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2019-03-29 16:31

MOT test number 926699182026

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-03-29 14:12

MOT test number 219808974895

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



MOT #2	2018-03-17 11:11
MOT test number	515565789984
Result	✓ Passed
MOT #1	2017-03-03 11:14
MOT test number	691662511869
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2023-09-28
Complete history	See info



Registration #1	2014-03-31	10 mi
Registration #2	2017-03-03	52.369 mi
Registration #3	2018-03-17	57.047 mi
Registration #4	2019-03-29	65.694 mi
Registration #5	2019-03-29	65.694 mi
Registration #6	2020-10-01	74.212 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1571 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CFFBJ60204