



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY D
Colour	White
Year of manufacture	2013
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E









Internet history

Entry 1

Date	2021-07-02
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-15
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #13	2023-07-14 11:09
MOT test number	514562544141
Result	✓ Passed
Next expiry date	2024-07-15

MOT #12	2022-07-14 11:03
MOT test number	770758797889
Result	✓ Passed

MOT #11	2021-07-16 14:57
MOT test number	412121289422
Result	✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10	2020-09-11 11:07
MOT test number	429021236676
Result	✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2019-07-29 16:21**MOT test number** 817593110526**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2019-07-29 15:51**MOT test number** 754091058456**Result** ✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))

**MOT #7** 2019-07-29 12:24**MOT test number** 332648178347**Result** ✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))

**MOT #6** 2019-07-29 12:17**MOT test number** 175478127156**Result** ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))



**MOT #5** 2018-08-24 14:34**MOT test number** 773961093410**Result** ✓ Passed**MOT #4** 2018-08-23 07:40**MOT test number** 784218176343**Result** ✗ Failed**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Minor** Front Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #3** 2017-04-28 15:20**MOT test number** 676235409147**Result** ✓ Passed**MOT #2** 2017-04-27 10:31**MOT test number** 270792481987**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit inner edge close to cord (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Items removed from driver's view prior to test**MOT #1** 2016-04-28 15:12**MOT test number** 853351312616**Result** ✓ Passed**Advice** Both rear tyres stepping inner edge**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
15 July 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	15 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>VO13XPD</b>
Plate since	2019-06-29
Current registration	<b>VO13XPD</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-02
Last registration	2023-07-14
Complete history	<a href="#">See info</a>



Registration #1	2013-05-02	14 mi
Registration #2	2016-04-28	35.091 mi
Registration #3	2017-04-27	48.042 mi
Registration #4	2017-04-28	48.074 mi
Registration #5	2018-08-23	58.179 mi
Registration #6	2018-08-24	58.183 mi
Registration #7	2019-07-29	72.399 mi
Registration #8	2019-07-29	72.399 mi
Registration #9	2020-05-20	75.277 mi
Registration #10	2020-05-20	75.277 mi
Registration #11	2020-05-20	75.277 mi
Registration #12	2020-05-20	75.277 mi
Registration #13	2020-05-20	75.277 mi
Registration #14	2020-05-20	75.277 mi
Registration #15	2020-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4802 mm
Wheel base	2710 mm
Kerb weight	1471 kg
Max. allowed weight	2070 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2

Engine number

CFFBH89030