



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SPORT
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-26
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-26
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	23
Total items failed	12

MOT #17	2023-07-27 12:31
MOT test number	766521208470
Result	✓ Passed
Next expiry date	2024-07-26

MOT #16	2023-07-26 14:31
MOT test number	832137666699

Result	✗ Failed
---------------	----------

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Minor** Nearside Rear Registration plate lamp insecure (4.7.1 (c) (i))

**MOT #15**

2021-08-10 15:25

MOT test number

889245092427

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14**

2021-08-05 15:38

MOT test number

952286712251

Result

✗ Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2020-11-06 12:07

MOT test number

394768495496

Result

✓ Passed

MOT #12

2020-11-05 17:49

MOT test number

790000314943

Result

✗ Failed

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Emissions not tested Excessive amount of smoke / Recommend service (8.2.2.2 (e))**Fail** Offside Front Headlamp aim too low (4.1.2 (a))**Fail** Exhaust emits visible black smoke at idle (8.2.1.2 (f))

**MOT #11** 2019-11-15 08:45**MOT test number** 511433108406**Result** ✓ Passed

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front rear arm bushes (5.3.4 (a) (i))

MOT #10 2019-11-15 08:45**MOT test number** 435975106228**Result** ✗ Failed

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front rear arm bushes (5.3.4 (a) (i))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #9 2019-01-23 14:56**MOT test number** 661363385887**Result** ✓ Passed

Advice Both rear trim sections missing

MOT #8 2017-11-09 12:38**MOT test number** 847748925620**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-11-09 10:38**MOT test number** 343604879921**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-11-11 11:31**MOT test number** 787728634219**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-11-04 15:29**MOT test number** 487170558070**Result** ✓ Passed**MOT #4** 2014-09-19 10:32**MOT test number** 266642464208**Result** ✓ Passed**MOT #3** 2013-10-22 14:00**MOT test number** 456025993223**Result** ✓ Passed**MOT #2** 2012-10-17 16:00**MOT test number** 297011692278**Result** ✓ Passed



MOT #1	2012-03-10 10:56
MOT test number	825530772016
Result	✓ Passed
Notice	Front wipers slightly smearing screen
Notice	Under-trays fitted obscuring some underside components
Notice	Oil leak



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-31
Last registration	2023-07-27
Complete history	See info



Registration #1	2009-03-31	13 mi
Registration #2	2012-03-10	15.182 mi
Registration #3	2012-10-17	18.801 mi
Registration #4	2013-10-22	28.178 mi
Registration #5	2014-09-19	38.545 mi
Registration #6	2015-11-04	55.109 mi
Registration #7	2016-11-11	62.829 mi
Registration #8	2017-11-09	69.303 mi
Registration #9	2017-11-09	69.303 mi
Registration #10	2019-01-23	74.896 mi
Registration #11	2019-01-23	74.896 mi
Registration #12	2019-01-23	74.896 mi
Registration #13	2019-01-23	74.896 mi
Registration #14	2019-01-23	74.896 mi
Registration #15	2019-01-23	74.896 mi
Registration #16	2019-01-23	74.896 mi
Registration #17	2019-01-23	74.896 mi
Registration #18	2019-01-23	74.896 mi
Registration #19	2019-01-23	74.896 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	644153
---------------	--------