



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE
Colour	White
Year of manufacture	2016
Top speed	107 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-07-22
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-18
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #8	2024-01-16 07:51
MOT test number	114104784077
Result	✓ Passed
Next expiry date	2025-01-18
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #7	2023-01-18 12:57
MOT test number	245142535665
Result	✓ Passed
Advice	Rear leaf spring mountings modified.

MOT #6	2023-01-18 12:57
MOT test number	181946768154
Result	✗ Failed
Advice	Rear leaf spring mountings modified.
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #5	2022-01-05 16:23
MOT test number	224388245031
Result	✓ Passed

**MOT #4** 2021-01-19 15:14**MOT test number** 346261078526**Result** ✓ Passed**Minor** Offside Rear Tyre obviously under inflated has nail in tyre and is worn inside edge (5.2.3 (I))**Advice** Spare tyre defective no pressure**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both on 3mm bald inside edges and splitting inner sidewalls (5.2.3 (e))**MOT #3** 2021-01-19 15:14**MOT test number** 492502549538**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Spare tyre defective no pressure**Minor** Offside Rear Tyre obviously under inflated has nail in tyre and is worn inside edge (5.2.3 (I))**Advice** Front Tyre worn close to legal limit/worn on edge both on 3mm bald inside edges and splitting inner sidewalls (5.2.3 (e))**MOT #2** 2020-03-20 12:41**MOT test number** 416105329520**Result** ✓ Passed**MOT #1** 2019-03-23 13:51**MOT test number** 944106721992**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
18 January 2025

Tax status		Valid until 1 September
Days left		126
MOT expiry date		18 January 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL16BVX
Plate since	2019-06-29
Current registration	 GL16BVX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-07
Last registration	2024-01-16
Complete history	See info



Registration #1	2016-07-07	10 mi
Registration #2	2019-03-23	77.422 mi
Registration #3	2020-03-20	86.027 mi
Registration #4	2021-01-19	90.687 mi
Registration #5	2021-01-19	90.687 mi
Registration #6	2022-05-20	95.277 mi
Registration #7	2022-05-20	95.277 mi
Registration #8	2023-05-20	95.277 mi
Registration #9	2023-05-20	95.277 mi
Registration #10	2024-01-16	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1823 mm
Length	4408 mm
Wheel base	2682 mm
Kerb weight	1472 kg
Max. allowed weight	2141 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles

2

Engine number

DFSD080105
