



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------|
| Make | HYUNDAI |
| Model | SANTA FE CRTD LIMITED 7STR |
| Colour | Blue |
| Year of manufacture | 2009 |
| Top speed | 110 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 155 BHP |
| Max. torque | 335 Nm at 2.500 rpm |
| Engine capacity | 2.188 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 25.2 mpg |
| Consumption extra urban | 42.8 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 212 g/km |
| CO2 label | K |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-03-29 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 8 |
| Total items failed | 4 |

MOT #13 2022-03-23 14:49

MOT test number 700061038229

Result ✓ Passed

Next expiry date 2023-03-29

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2022-03-23 14:49

MOT test number 824664032238

Result ✗ Failed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2021-03-30 21:34

MOT test number 372374111050

Result ✓ Passed



| | |
|----------------|------------------|
| MOT #10 | 2021-03-30 15:24 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 606571287567 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✗ Failed |
|---------------|----------|

| | |
|--------------------------------|---|
| Pass with rectification | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) |
|--------------------------------|---|

| | |
|-------------|---|
| Fail | Windscreen washer not working (3.5 (a)) |
|-------------|---|

| | |
|---------------|------------------|
| MOT #9 | 2020-02-12 12:57 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 382500948533 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #8 | 2019-02-08 16:17 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 345940139895 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #7 | 2018-02-08 10:28 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 520285794150 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #6 | 2017-02-07 14:05 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 387938729042 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2015-12-30 11:15 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 123756433440 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2014-10-01 10:55 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 339704274441 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



| | |
|-----------------|--|
| MOT #3 | 2013-10-11 12:01 |
| MOT test number | 288094683268 |
| Result | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay |
| Notice | Under-trays fitted obscuring some underside components |

| | |
|-----------------|--|
| MOT #2 | 2013-09-24 11:32 |
| MOT test number | 517187963269 |
| Result | ✗ Failed |
| Fail | Power steering component(s) leaking (2.3.3b) |

| | |
|-----------------|------------------|
| MOT #1 | 2012-09-28 10:15 |
| MOT test number | 989782772294 |
| Result | ✓ Passed |



Tax & MOT check

X

Untaxed

Tax expired:
22 March 2022

X

MOT

Expired:
29 March 2023

| | |
|------------------|---------------------------------|
| Tax status | Expired at 22 March 2022 |
| Days left | 768 days too late |
| MOT expiry date | 29 March 2023 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2009-07-01 |
| Last registration | 2022-03-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-07-01 | 15 mi |
| Registration #2 | 2012-09-28 | 18.962 mi |
| Registration #3 | 2013-09-24 | 23.075 mi |
| Registration #4 | 2013-10-11 | 23.431 mi |
| Registration #5 | 2014-10-01 | 29.866 mi |
| Registration #6 | 2015-12-30 | 37.380 mi |
| Registration #7 | 2017-02-07 | 45.971 mi |
| Registration #8 | 2019-05-29 | 55.277 mi |
| Registration #9 | 2019-05-29 | 55.277 mi |
| Registration #10 | 2019-05-29 | 55.277 mi |
| Registration #11 | 2019-05-29 | 55.277 mi |
| Registration #12 | 2019-05-29 | 55.277 mi |
| Registration #13 | 2019-05-29 | 55.277 mi |
| Registration #14 | 2019-05-29 | 55.277 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1890 mm |
| Height | 1725 mm |
| Length | 4650 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1893 kg |
| Max. allowed weight | 2570 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 75 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Engine number

D4EB7358804