



**SJ60UJO**

report date: 2024-03-29

General information

Make	FORD
Model	FIESTA STYLE PLUS TDCI
Colour	White
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg





Internet history

Entry 1

Date	2021-06-10
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #17</b>	2022-09-05 08:27
<b>MOT test number</b>	105637449799
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-09-08
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
<b>Advice</b>	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

<b>MOT #16</b>	2022-09-05 08:27
<b>MOT test number</b>	778485559215
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))

<b>MOT #15</b>	2021-09-09 12:14
<b>MOT test number</b>	309345883416
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2021-09-08 12:30
<b>MOT test number</b>	268437412564
<b>Result</b>	✗ Failed
<b>Fail</b>	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))



MOT #13

2020-10-12 16:31

MOT test number

504518510159

Result

✓ Passed

- Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated wishbone (5.3.4 (b) (i))
- Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated wishbone (5.3.4 (b) (i))
- Minor

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #12**

2020-10-12 16:31

**MOT test number**

275953348417

**Result**

✗ Failed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated wishbone (5.3.4 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated wishbone (5.3.4 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #11**

2019-10-22 12:57

**MOT test number**

236688742686

**Result**

✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10**

2018-10-24 13:10

**MOT test number**

177491299568

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2018-10-18 12:03**MOT test number** 184356534753**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #8** 2017-10-23 11:49**MOT test number** 111057343168**Result** ✓ Passed**MOT #7** 2016-09-26 16:00**MOT test number** 524403346698**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Steering system has slight free play detected at steering wheel track rod has play (2.2.A.1b)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #6** 2016-09-26 13:39**MOT test number** 419585845700**Result** ✗ Failed**Advice** Nearside Front Steering system has slight free play detected at steering wheel track rod has play (2.2.A.1b)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2015-10-01 13:41**MOT test number** 990127939131**Result** ✓ Passed**Advice** Rear exhaust box corroded**MOT #4** 2014-09-18 16:01**MOT test number** 889001464262**Result** ✓ Passed**Notice** Rear exhaust corroded**MOT #3** 2014-09-18 11:15**MOT test number** 385141264239**Result** ✗ Failed**Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)**Fail** Indicator switch faulty (1.4.A.1)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Steering column movement between the shaft and steering wheel (2.1.2b)



MOT #2	2013-08-31 16:03
MOT test number	265683243209
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-08-31 16:03
MOT test number	628593343243
Result	✗ Failed
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Front Headlamp aim too high (1.8)





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-30
Last registration	2022-09-05
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	17 mi
Registration #2	2013-08-31	63.740 mi
Registration #3	2014-09-18	78.385 mi
Registration #4	2014-09-18	78.385 mi
Registration #5	2015-10-01	88.487 mi
Registration #6	2016-09-26	112.564 mi
Registration #7	2016-09-26	112.564 mi
Registration #8	2017-10-23	124.291 mi
Registration #9	2018-10-18	133.102 mi
Registration #10	2019-09-20	151.377 mi
Registration #11	2019-09-20	151.377 mi
Registration #12	2019-09-20	151.377 mi
Registration #13	2019-09-20	151.377 mi
Registration #14	2019-09-20	151.377 mi
Registration #15	2019-09-20	151.377 mi
Registration #16	2019-09-20	151.377 mi
Registration #17	2019-09-20	151.377 mi
Registration #18	2019-09-20	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1141 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2

**Engine number**

9R21853