





report date: 2024-03-28

General information

Make	BMW
Model	525 525D SE
Colour	Blue
Year of manufacture	-
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg



CarCheck.co.uk page 1/12



MOT history

MOT #	19	2020-12-02 15:49
MOT te	st number	434262043237
Result		✓ Passed
Next ex	xpiry date	2021-12-01
MOT #	18	2020-12-02 10:51
MOT te	est number	568728984122
Result		★ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #17		2019-11-08 07:40
MOT test	number	278246849857
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16		2019-01-16 12:14
MOT test	number	988904879086
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Exhaust emits blue smoke during acceleration (8.2.1.2 (g))	

CarCheck.co.uk page 2/12



MOT #15 2019-01-16 12:14

MOT test number 756026317638

Result X Failed

Advice Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #14 2018-01-18 17:50

MOT test number 594597409103

Result ✓ Passed

Advice Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #13 2016-03-17 15:06

MOT test number 565426213031

MOT #12 2016-03-17 12:31

MOT test number 398249035449

Result X Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Fail Rear rear parking brake recording little or no effort (3.7.B.6a)

CarCheck.co.uk page 3/12



MOT #11 2015-03-18 14:36

MOT test number 129997575000

Result ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Trailing arm has slight play in a ball joint (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #10 2015-03-16 13:41

MOT test number 417135175015

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front Brake hose excessively chafed (3.6.B.4d)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #9 2014-03-18 15:49

MOT test number 349687374069

CarCheck.co.uk page 4/12



MOT #8 2014-03-18 12:46

MOT test number 245707074073

Result × Failed

Fail Offside Rear Suspension arm has excessive play in a pin/bush (2.4.G.2)

Fail Brake fluid warning lamp illuminated (3.6.G.2)

MOT #7 2013-09-23 11:41

MOT test number 815446663294

Result ✓ Passed

MOT #6 2012-09-25 15:46

MOT test number 876819062289

Result \(\sqrt{Passed} \)

MOT #5 2011-06-20 15:51

MOT test number 256661071105

MOT #4 2010-07-01 18:34

MOT test number 833402480149

MOT #3 2009-07-01 10:03

MOT test number 952052689154

Result

Passed

MOT #2 2008-07-09 13:42

MOT test number 860281798133

CarCheck.co.uk page 5/12



MOT #1 2008-02-13 13:43

MOT test number 412044648085

Result ✓ Passed

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ve?

THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-11
Last registration	2020-12-02
Complete history	See info



Registration #1	2005-03-11	26 mi
Registration #2	2008-02-13	68.561 mi
Registration #3	2008-07-09	73.709 mi
Registration #4	2009-07-01	88.102 mi
Registration #5	2010-07-01	96.661 mi
Registration #6	2011-06-20	114.291 mi
Registration #7	2012-09-25	132.672 mi
Registration #8	2013-09-23	145.003 mi
Registration #9	2014-03-18	150.969 mi
Registration #10	2014-03-18	150.969 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777-es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1660 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12