





report date: 2024-03-29

General information

Make	VAUXHALL	
Model	COMBO 2000 L1H1 CDTI	
Colour	White	
Year of manufacture	2016	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	89 BHP	
Max. torque	200 Nm at 1.500 rpm	
Engine capacity	1.248 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	43.5 mpg	
Consumption extra urban	67.3 mpg	
Consumption combined	56.5 mpg	
CO2 emission	133 g/km	
CO2 label	E	



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1


Date 2021-07-01

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	8

MOT #9		2023-07-21 10:47
MOT test	number	854028959178
Result		✓ Passed
Next expiry date 2024-07-2		2024-07-20
Advice	Offside Front Seat belt buckle slightly damaged (7.1.2 (d))	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or co	ords (5.2.3 (d) (i))

MOT #8	2023-07-18 08:12	
MOT test number	856222076259	
Result	X Failed	
Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d))		
Fail Nearside Headlamp levelling device inoperative (4.1.5 (a))		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.	3 (d) (i))	

MOT #7	2022-07-01 14:47
MOT test number	101392821762
Result	√ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

426075446556

Result

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail

Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))

 MOT #5
 2021-07-21 07:51

 MOT test number
 373569538812

 Result
 ✓ Passed

MOT test number

Result

Rear fog lamp switch inoperative (4.5.3 (a))

Fail Hazard warning switch inoperative (4.4.2 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2

MOT test number

Result

Advice

Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1

MOT test number

431200921608

Result

Advice Offside Front tyre warn inner edge

Advice Nearside Rear tyre perished outer wall

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history

o mile. History	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-06-30
Last registration	2023-07-21
Complete history	See info



Registration #1	2016-06-30	16 mi
Registration #2	2019-06-29	51.712 mi
Registration #3	2020-06-03	63.308 mi
Registration #4	2021-05-25	85.698 mi
Registration #5		11.777 es
Registration #6	2021-07-15	85.715 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 66
Registration #11		0.00 es

More info >

CarCheck.co.uk page 11/12



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A2000-5824911

CarCheck.co.uk page 12/12