




report date: 2024-03-29

General information

Make	MINI
Model	COOPER CLUBMAN
Colour	Silver
Year of manufacture	2013
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





**Internet history**

**Entry 1**

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](http://autoonline.co.uk)



MOT history

MOT expiry date	2025-01-04
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	24
Total items failed	4

<b>MOT #10</b>	2024-01-05 09:51
MOT test number	422835166373
Result	✓ Passed
Next expiry date	2025-01-04

<b>MOT #9</b>	2022-12-06 09:41
MOT test number	713795755672
Result	✓ Passed
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #8</b>	2021-12-07 09:10
MOT test number	393234869335
Result	✓ Passed

<b>MOT #7</b>	2020-12-11 15:59
MOT test number	552581543569
Result	✓ Passed



MOT #6 2020-06-25 10:06

MOT test number 447580823940

Result ✔ Passed

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing close to wear indicators (5.2.3 (e))

MOT #5 2019-04-02 12:23

MOT test number 206559585722

Result ✔ Passed

**Advice** Nearside Hydraulic leak, but not excessive drive shaft oil seal (8.4.1 (a) (i))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #4 2019-04-02 09:04

MOT test number 164481063201

Result ✘ Failed

**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Hydraulic leak, but not excessive drive shaft oil seal (8.4.1 (a) (i))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



<b>MOT #3</b>	2017-09-26 12:12
<b>MOT test number</b>	354407571718
<b>Result</b>	✓ Passed
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
<b>Advice</b>	Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
<b>Advice</b>	Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

<b>MOT #2</b>	2017-09-25 11:37
<b>MOT test number</b>	555191576349
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Outer Brake pad(s) wearing thin 2mm (3.5.1g)
<b>Advice</b>	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Oil level below min
<b>Advice</b>	Nearside Front front brake fluctuating, but not excessively (3.7.B.3)
<b>Advice</b>	Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
<b>Fail</b>	Nearside Front Road wheel fixings not compatible 2 Wheel bolts missing (4.2.B.2)
<b>Advice</b>	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
<b>Pass with rectification</b>	Nearside Headlamp aim too low (1.8)
<b>Advice</b>	Offside Front Inner Tyre worn
<b>Fail</b>	Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
<b>Advice</b>	Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)



**MOT #1** 2016-09-26 10:41

**MOT test number** 575382048947

**Result** ✓ Passed

**Advice** Oil leak sump area

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
4 January 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	4 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YH63PUY
Plate since	2024-03-29
Current registration	YH63PUY
Plate since	2024-03-29

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-30
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2013-09-30	14 mi
Registration #2	2016-09-26	20.418 mi
Registration #3	2017-09-25	29.086 mi
Registration #4	2017-09-26	29.090 mi
Registration #5	2019-04-02	45.668 mi
Registration #6	2019-04-02	45.668 mi
Registration #7	2019-04-02	45.668 mi
Registration #8	2019-04-02	45.668 mi
Registration #9	2019-04-02	45.668 mi
Registration #10	2019-04-02	45.668 mi
Registration #11	2019-04-02	45.668 mi
Registration #12	2019-04-02	45.668 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3937 mm
Wheel base	2547 mm
Kerb weight	1145 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

A402J564