



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC AWD D5 SE LUX
Colour	Silver
Year of manufacture	2005
Top speed	121 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg
CO2 emission	223 g/km
CO2 label	K





Internet history

Entry 1	
Date	2021-06-11
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	58
Total items failed	7

MOT #22	2024-03-30 10:17
MOT test number	877653286170
Result	✓ Passed
Next expiry date	2025-03-29
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Exhaust mounting defective Back box support bracket broken (6.1.2 (a))
Advice	All rear susspension component corrosion
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #21**

2024-03-25 12:00

MOT test number

119143362970

Result**✗ Failed**

- MAJOR** Front Service brake excessively binding Both side (1.2.1 (f))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Brake performance unable to be tested (1.2.1 (g))
- MAJOR** Front Position lamp not working Both side (4.2.1 (a) (ii))
- MAJOR** Headlamp aim unable to be tested Both (4.1.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Exhaust mounting defective Back box support bracket broken (6.1.2 (a))
- MAJOR** Headlamp lens seriously defective Both side (4.1.1 (b) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Front Headlamp not working on dipped beam Both side (4.1.1 (a) (ii))
- Advice** All rear suspension component corrosion

**MOT #20**

2023-03-24 09:52

MOT test number

623219997419

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** All rear suspension components corroded
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both headlights deteriorated (4.1.4 (b))

MOT #19

2022-03-25 10:00

MOT test number

631684306391

Result

✓ Passed

- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both headlights deteriorated (4.1.4 (b))
- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Rear Coil spring corroded both springs corroded (5.3.1 (b) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))
- Advice** Ns parking brake efficiency low
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #18** 2021-03-18 10:30**MOT test number** 100443703145**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Undertrays fitted**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2020-03-30 08:50**MOT test number** 262207270114**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #16** 2020-03-30 08:50**MOT test number** 183359185575**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15** 2019-02-28 12:57**MOT test number** 281310126284**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rubber bush (5.3.4 (a) (i))

**MOT #14** 2019-02-25 09:56**MOT test number** 407627159717**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rubber bush (5.3.4 (a) (i))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #13** 2018-03-08 11:48**MOT test number** 982879853689**Result** ✓ Passed**MOT #12** 2017-03-03 16:31**MOT test number** 547137500666**Result** ✓ Passed**MOT #11** 2016-01-20 11:57**MOT test number** 739651716133**Result** ✓ Passed**MOT #10** 2015-02-13 16:04**MOT test number** 496404945087**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2015-02-13 16:04**MOT test number** 556614045031**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2014-02-18 13:16**MOT test number** 435399244025**Result** ✓ Passed**MOT #7** 2013-02-01 15:48**MOT test number** 168612633088**Result** ✓ Passed**MOT #6** 2012-02-07 10:01**MOT test number** 998178432090**Result** ✓ Passed**MOT #5** 2011-02-23 15:26**MOT test number** 309374151025**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4**

2011-02-21 09:30

MOT test number

139722151445

Result**✗ Failed****Notice** Front brake discs thin and corroded rear brake discs thin and corroded**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Headlamp aim too low (1.8)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3**

2010-10-06 17:00

MOT test number

900339070281

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2**

2009-10-02 11:23

MOT test number

164865579223

Result**✓ Passed**



MOT #1	2008-09-15 17:06
MOT test number	254419058239
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
29 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-05-29
Current registration	 
Plate since	2019-05-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-30
Last registration	2024-03-30
Complete history	See info



Registration #1	2005-09-30	23 mi
Registration #2	2008-09-15	29.470 mi
Registration #3	2009-10-02	39.333 mi
Registration #4	2010-10-06	48.037 mi
Registration #5	2011-02-21	51.102 mi
Registration #6	2011-02-23	51.102 mi
Registration #7	2012-02-07	60.334 mi
Registration #8	2013-02-01	68.132 mi
Registration #9	2014-02-18	76.692 mi
Registration #10	2015-02-13	85.659 mi
Registration #11	2016-01-20	93.722 mi
Registration #12	2017-03-03	103.009 mi
Registration #13	2018-03-20	111.377 mi
Registration #14	2019-03-20	121.377 mi
Registration #15	2020-03-20	131.377 mi
Registration #16	2021-03-20	141.377 mi
Registration #17	2022-03-20	151.377 mi
Registration #18	2023-03-20	161.377 mi
Registration #19	2024-03-20	171.377 mi
Registration #20	2025-03-20	181.377 mi
Registration #21	2026-03-20	191.377 mi
Registration #22	2027-03-20	201.377 mi
Registration #23	2028-03-20	211.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1860 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1748 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	294972