




report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	15
Total items failed	13

MOT #16	2023-07-25 09:54
MOT test number	695263190968
Result	✓ Passed
Next expiry date	2024-07-27

MOT #15	2022-07-28 10:32
MOT test number	445883926638
Result	✓ Passed

MOT #14	2022-07-28 10:32
MOT test number	304043434128
Result	✗ Failed
<div style="border: 1px solid #ccc; padding: 5px;"> Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii)) </div>	

MOT #13	2021-07-20 13:42
MOT test number	344265494735
Result	✓ Passed



MOT #12	2021-07-19 15:28
MOT test number	200886587437
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #11	2020-07-21 13:43
MOT test number	555427816720
Result	✓ Passed

MOT #10	2020-07-20 12:00
MOT test number	302475478448
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9	2019-07-05 15:16
MOT test number	858958724053
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #8	2019-07-04 10:59
MOT test number	675675817077
Result	✗ Failed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn Rear bush. (5.3.4 (a) (i))
Fail	Front Brakes imbalanced across an axle (1.2.1 (b) (i))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush. (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside front. (1.1.14 (a) (ii))

MOT #7	2018-07-11 11:45
MOT test number	844058255618
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)

MOT #5	2016-07-05 13:57
MOT test number	853597171941
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Nail in tyre



MOT #4 2015-07-07 08:36

MOT test number 265968585479

Result ✓ Passed

MOT #3 2015-06-01 14:53

MOT test number 225922055488

Result ✓ Passed

Advice Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Near side front tyre side wall cut but not showing cord.

MOT #2 2015-06-01 13:19

MOT test number 166122655192

Result ✗ Failed

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Near side front tyre side wall cut but not showing cord.

Fail Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)

MOT #1 2014-05-07 10:18

MOT test number 399677124185

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
27 July 2024

Tax status Valid until 1 August

Days left 94

MOT expiry date 27 July 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SM11RWV
Plate since	2019-09-29
Current registration	SM11RWV
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-06-17
Last registration	2023-07-25
Complete history	See info



Registration #1	2011-06-17	27 mi
Registration #2	2014-05-07	19.399 mi
Registration #3	2015-06-01	25.471 mi
Registration #4	2015-06-01	25.744 mi
Registration #5	2015-07-07	26.312 mi
Registration #6	2016-07-05	30.158 mi
Registration #7	2017-07-19	33.853 mi
Registration #8	2018-07-11	36.742 mi
Registration #9	2019-07-04	41.619 mi
Registration #10	2020-06-22	45.277 mi
Registration #11	2021-06-22	48.277 mi
Registration #12	2022-06-22	51.277 mi
Registration #13	2023-06-22	54.277 mi
Registration #14	2023-06-22	57.277 mi
Registration #15	2023-06-22	60.277 mi
Registration #16	2023-06-22	63.277 mi
Registration #17	2023-06-22	66.277 mi
Registration #18	2023-06-22	69.277 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212