



MT63TKE

report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | LAND ROVER |
| Model | FREELANDER SD4 HSE LUXURY |
| Colour | Black |
| Year of manufacture | 2013 |
| Top speed | 118 mph |
| 0 - 100 km/h | 11.2 seconds |
| 0 - 60 mph | 8.7 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 110 kW / 150 HP / 190 BHP |
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-07 |
| Pictures | 10 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-04 |
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 15 |
| Total items failed | 4 |

| | |
|------------------|--|
| MOT #11 | 2023-12-28 11:16 |
| MOT test number | 879444150349 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-04 |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #10 | 2022-12-29 12:49 |
| MOT test number | 261786415251 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #9 | 2022-01-05 15:20 |
| MOT test number | 193390226568 |
| Result | ✓ Passed |

**MOT #8** 2021-04-10 12:22**MOT test number** 764826266425**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7** 2021-04-08 10:29**MOT test number** 238262610415**Result** ✗ Failed**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #6** 2019-11-01 16:30**MOT test number** 652977042422**Result** ✓ Passed**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin both front (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #5** 2018-10-29 16:25**MOT test number** 273455016517**Result** ✓ Passed

**MOT #4** 2018-10-29 11:12**MOT test number** 185151962352**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2017-11-17 09:31**MOT test number** 349769831765**Result** ✓ Passed**MOT #2** 2016-11-24 14:14**MOT test number** 347161339591**Result** ✓ Passed**MOT #1** 2016-11-24 14:14**MOT test number** 310467735376**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 248 |
| MOT expiry date | 4 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | MT63TKE |
| Plate since | 2024-03-28 |
| Current registration | MT63TKE |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2013-11-29 |
| Last registration | 2023-12-28 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-11-29 | 23 mi |
| Registration #2 | 2016-11-24 | 25.378 mi |
| Registration #3 | 2016-11-24 | 25.378 mi |
| Registration #4 | 2017-11-17 | 33.015 mi |
| Registration #5 | 2018-10-29 | 35.063 mi |
| Registration #6 | 2018-10-29 | 35.063 mi |
| Registration #7 | 2019-11-01 | 47.440 mi |
| Registration #8 | 2019-11-01 | 47.440 mi |
| Registration #9 | 2019-11-01 | 47.440 mi |
| Registration #10 | 2019-11-01 | 47.440 mi |
| Registration #11 | 2019-11-01 | 47.440 mi |
| Registration #12 | 2019-11-01 | 47.440 mi |
| Registration #13 | 2019-11-01 | 47.440 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2180 mm |
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1770 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 68 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DZ784152302224DT |