



ST050KC

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	LUPO E
Colour	Blue
Year of manufacture	-
Top speed	94 mph
0 - 60 mph	17.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	50 BHP
Max. torque	86 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT #21</b>	2021-05-17 12:21
<b>MOT test number</b>	951443100977
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-05-16

<b>MOT #20</b>	2019-06-04 07:11
<b>MOT test number</b>	532875591241
<b>Result</b>	✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material nearside front to rear, at rear (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2019-05-30 09:51

**MOT test number**

603214299783

**Result**

✗ Failed

- Advice** Brake pipe corroded, covered in grease or other material nearside front to rear, at rear (1.1.11 (c))
- Fail** Service brake excessively binding both rear (1.2.1 (f))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Exhaust has a major leak of exhaust gases front flexi, cat, rear silencer (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Driver's door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Gear selector stiff
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #18**

2018-06-06 15:23

**MOT test number**

485547524411

**Result**

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material down leg (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive engine area (8.4.1 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2018-06-06 08:28

**MOT test number**

217912710590

**Result**

✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material down leg (1.1.11 (c))
- Advice** Little reserve travel parking brake
- Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive engine area (8.4.1 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #16**

2017-06-14 14:49

**MOT test number**

884542766204

**Result**

✓ Passed

- Advice** Nearside Rear slight noise - possible bearing
- Advice** Items removed from driver's view prior to test stickers and air freshners
- Advice** Both number plates slightly deteriorated
- Advice** Offside Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Both rear shock absorber dust covers insecure
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #15**

2017-06-13 08:27

**MOT test number**

943674118913

**Result****✗ Failed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Front exhaust sleeve in poor condition - heavily corroded
- Fail** Central Exhaust has a major leak of exhaust gases corroded and holed (7.1.2)
- Advice** Both rear shock absorber dust covers insecure
- Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- Advice** Items removed from driver's view prior to test stickers and air freshners
- Advice** Both number plates slightly deteriorated
- Fail** Battery insecure (1.9.1)
- Fail** Nearside Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Offside Rear wheel bearing not fully tested due to seized brake
- Fail** Offside rear brake binding (3.7.B.1)
- Advice** Nearside Rear slight noise - possible bearing
- Advice** Nearside Non obligatory mirror damaged glass broken
- Advice** Both number plates slightly deteriorated
- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)

**MOT #14**

2016-05-31 15:22

**MOT test number**

233018257162

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit 175/65/13 and showing perishing (4.1.E.1)
- Advice** Nearside Rear Brake pipe slightly corroded down leg (3.6.B.2c)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear of front (2.4.G.2)
- Advice** Brake pipe slightly corroded both front to rear at rear (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded down leg (3.6.B.2c)

**MOT #13**

2016-05-31 12:40

**MOT test number**

751419428771

**Result**

✗ Failed

- Advice** Offside Rear Brake pipe slightly corroded down leg (3.6.B.2c)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit 175/65/13 and showing perishing (4.1.E.1)
- Advice** Nearside Rear Brake pipe slightly corroded down leg (3.6.B.2c)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear of front (2.4.G.2)
- Advice** Brake pipe slightly corroded both front to rear at rear (3.6.B.2c)

**MOT #12**

2015-06-04 16:20

**MOT test number**

936555055184

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #11	2015-06-03 09:46
MOT test number	628714255174
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #10	2014-06-19 13:44
MOT test number	795890074177
Result	✓ Passed
Notice	Slight judder from front and rear brakes
Notice	Slight leak from exhaust clamp / sleeve
Notice	EPC light on
Notice	Front brake discs corroded and slight pitting
Notice	Rear shock absorber dust covers insecure



**MOT #9**

2014-06-18 14:03

**MOT test number**

296219564149

**Result****✗ Failed**

- Fail** Nearside rear brake recording little or no effort (3.7.B.5a)
- Notice** Slight judder from front and rear brakes
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Slight leak from exhaust clamp / sleeve
- Fail** Brakes imbalanced across an axle (3.7.B.5b)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** Front brake discs corroded and slight pitting
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Rear shock absorber dust covers insecure

**MOT #8**

2013-05-30 15:14

**MOT test number**

347920053117

**Result****✓ Passed**

- Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #7**

2013-05-29 09:02

**MOT test number**

129159243125

**Result****✗ Failed**

- Fail** Centre Exhaust system not adequately supported (7.1.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Engine man light on
- Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #6**

2012-06-22 16:38

**MOT test number**

885354072163

**Result****✓ Passed**

- Notice** Cat to centre pipe exhaust sleeve and clamps rusty
- Notice** O/s door check strap loose/broken
- Notice** Exhaust flexible section leaking
- Notice** Engine management light indicates a fault

**MOT #5** 2012-06-22 11:40**MOT test number** 257784372434**Result** ✗ Failed

- Notice** Engine management light indicates a fault
- Notice** Cat to centre pipe exhaust sleeve and clamps rusty
- Notice** O/s/r tyre perished and nail in outer shoulder of tread
- Notice** O/s door check strap loose/broken
- Notice** Exhaust flexible section leaking

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #4** 2011-05-05 11:55**MOT test number** 835105421162**Result** ✓ Passed

- Notice** Offside rear tyre perished

**MOT #3** 2010-04-30 10:24**MOT test number** 753350020122**Result** ✓ Passed

- Notice** Both rear tyres perished
- Notice** Nearside rear tyre soft

**MOT #2** 2009-04-23 11:39**MOT test number** 702073319147**Result** ✓ Passed**MOT #1** 2008-04-24 14:29**MOT test number** 192605218189**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-28
Current registration	 *****
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-13
Last registration	2021-05-17
Complete history	<a href="#">See info</a>



Registration #1	2005-05-13	20 mi
Registration #2	2008-04-24	13.514 mi
Registration #3	2009-04-23	22.060 mi
Registration #4	2010-04-30	32.683 mi
Registration #5	2011-05-05	43.501 mi
Registration #6	2012-06-22	54.178 mi
Registration #7	2012-06-22	54.178 mi
Registration #8	2013-05-29	61.827 mi
Registration #9	2013-05-30	61.829 mi
Registration #10	2014-06-18	63.746 mi
Registration #11	2014-06-19	63.746 mi
Registration #12	2015-06-03	70.117 mi
Registration #13	2016-06-03	70.117 mi
Registration #14	2016-06-03	70.117 mi
Registration #15	2016-06-03	70.117 mi
Registration #16	2016-06-03	70.117 mi
Registration #17	2016-06-03	70.117 mi
Registration #18	2016-06-03	70.117 mi
Registration #19	2016-06-03	70.117 mi
Registration #20	2016-06-03	70.117 mi
Registration #21	2016-06-03	70.117 mi
Registration #22	2016-06-03	70.117 mi
Registration #23	2016-06-03	70.117 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1860 mm
Height	1459 mm
Length	3527 mm
Wheel base	2321 mm
Kerb weight	946 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	34 l
Fuel delivery	Multi-Point Injection
Number of doors	3

**Number of seats**

4

**Engine number**

AUC275121