




report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT DDIS
Colour	Silver
Year of manufacture	2009
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-11
Pictures	14
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-06-27
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	16
Total items failed	6

MOT #12	2023-06-17 10:33
MOT test number	657239057138
Result	✓ Passed
Next expiry date	2024-06-27
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-06-28 16:18
MOT test number	155613579499
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear slightly binding
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2021-04-15 15:07
MOT test number	609425051262
Result	✓ Passed

**MOT #9**

2021-04-12 15:42

MOT test number

711136941940

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Vehicle fitted with under body protective trays and over sill covers obscuring underside components and /or vehicle rigidity from visual inspection**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #8**

2020-06-11 15:05

MOT test number

530117557471

Result**✓ Passed****Minor** Nearside Front Lower Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #7**

2019-05-14 14:45

MOT test number

492758182352

Result**✓ Passed****Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #6	2018-05-22 10:07
MOT test number	391301146330
Result	✓ Passed
Advice	Osf strut top mount slight play
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2017-05-17 13:04
MOT test number	104803007263
Result	✓ Passed

MOT #4	2016-05-12 12:22
MOT test number	978387530154
Result	✓ Passed

MOT #3	2015-05-21 16:43
MOT test number	279901745169
Result	✓ Passed

MOT #2	2014-05-23 16:43
MOT test number	918813744166
Result	✓ Passed

MOT #1	2012-10-18 11:54
MOT test number	617632992227
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
27 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-10-17
Last registration	2023-06-17
Complete history	See info



Registration #1	2009-10-17	29 mi
Registration #2	2012-10-18	20.227 mi
Registration #3	2014-05-23	24.958 mi
Registration #4	2015-05-21	28.161 mi
Registration #5	2016-05-12	31.418 mi
Registration #6	2017-05-17	34.721 mi
Registration #7	2018-05-22	39.436 mi
Registration #8	2019-05-27	44.149 mi
Registration #9	2020-05-27	48.862 mi
Registration #10	2021-05-27	53.575 mi
Registration #11	2022-05-27	58.288 mi
Registration #12	2023-05-27	62.999 mi
Registration #13	2024-05-27	67.712 mi
Registration #14	2025-05-27	72.425 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3760 mm
Wheel base	2380 mm
Max. allowed weight	1525 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D13A-1267598