



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Green
Year of manufacture	2004
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	121 BHP
Max. torque	170 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-23
Pictures	42
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-06-19
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	53
Total items failed	21

MOT #27 2023-06-07 14:54**MOT test number** 822932587707**Result** ✓ Passed**Next expiry date** 2024-06-19

- Advice** Offside Rear Parking brake performance poor.
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Rear Reverse lights not working.
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #26 2023-06-07 09:40**MOT test number** 910731377228**Result** ✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Reverse lights not working.
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint likely to become detached Detached. (5.3.4 (a) (ii))
- Fail** Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Parking brake performance poor.

**MOT #25**

2022-06-01 16:42

MOT test number

653695789945

Result

✓ Passed

Advice Nearside Rear Reverse light not working**Advice** Rear Direction indicator slightly discoloured Both rear indicator bulbs (4.4.3 (a))**MOT #24**

2022-06-01 09:38

MOT test number

673719760396

Result

✗ Failed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Both reverse lights not working**Advice** Rear Direction indicator slightly discoloured Both rear indicator bulbs (4.4.3 (a))**Advice** Rear Tyre worn close to legal limit/worn on edge Both rear tyres worn on inner edge (5.2.3 (e))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #23

2021-06-08 13:30

MOT test number

233816150560

Result

✓ Passed

- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Reverse light inoperative
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Nearside Outer unable to check sill for corrosion due to cover
- Advice

Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Nearside Rear Inner unable to check sill for corrosion due to cover
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Exhaust mounting defective (6.1.2 (a))
- Advice

Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Engine cover loose but not likely to fall off
- Advice

Rear Vehicle structure slightly corroded within 30cm of towbar mounting crossmember corroded but not holed (6.1.6 (i) (i))
- Advice

Offside Outer unable to check sill for corrosion due to cover
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Rear Inner unable to check sill for corrosion due to cover

**MOT #22**

2021-06-07 11:15

MOT test number

392912778152

Result**✗ Failed**

- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Rear Inner unable to check sill for corrosion due to cover
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Engine cover loose but not likely to fall off
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Outer unable to check sill for corrosion due to cover
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Inner unable to check sill for corrosion due to cover
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Reverse light inoperative
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Outer unable to check sill for corrosion due to cover
- Advice** Rear Vehicle structure slightly corroded within 30cm of towbar mounting crossmember corroded but not holed (6.1.6 (i) (i))

MOT #21

2020-06-03 16:02

MOT test number

808771870983

Result**✓ Passed**

- Advice** Reverse light inoperative

**MOT #20**

2020-06-02 08:06

MOT test number

406397387869

Result**✗ Failed****Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Reverse light inoperative**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #19**

2019-06-20 13:58

MOT test number

597801638148

Result**✓ Passed****Advice** Nearside Rear handbrake has poor reading**MOT #18**

2019-06-20 09:25

MOT test number

690167897830

Result**✗ Failed****Advice** Nearside Rear handbrake has poor reading**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Brake insecure back plate (1.1.21 (c))**MOT #17**

2018-06-08 13:05

MOT test number

659370058128

Result**✓ Passed**

**MOT #16** 2018-06-08 08:49**MOT test number** 454428877405**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #15** 2017-05-26 10:02**MOT test number** 934921749505**Result** ✓ Passed**MOT #14** 2017-05-25 10:18**MOT test number** 931241823724**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Both front tyres bald on inner shoulders**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #13** 2016-06-20 11:11**MOT test number** 870338591248**Result** ✓ Passed**MOT #12** 2016-06-15 10:54**MOT test number** 527156533337**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside rear brake binding (3.7.B.1)

**MOT #11** 2015-06-19 15:41**MOT test number** 956900375127**Result** ✓ Passed**MOT #10** 2015-06-15 09:54**MOT test number** 658466265185**Result** ✗ Failed

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Nearside Headlamp aim too far to the left (1.8)

Fail Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #9 2014-06-10 11:55**MOT test number** 725961664129**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #8 2013-06-20 09:50**MOT test number** 638351873158**Result** ✓ Passed**MOT #7** 2012-11-02 09:15**MOT test number** 169877302328**Result** ✓ Passed**MOT #6** 2011-11-25 09:43**MOT test number** 695579621341**Result** ✓ Passed



MOT #5	2011-10-12 09:43
---------------	------------------

MOT test number	815975181225
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2010-09-28 11:30
---------------	------------------

MOT test number	781621170250
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2009-09-29 15:19
---------------	------------------

MOT test number	972902779217
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
---------------	---

MOT #2	2008-09-18 14:06
---------------	------------------

MOT test number	443282568266
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-09-26 15:43
---------------	------------------

MOT test number	533139467267
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:
15 March 2024

✓

MOT

Expires:
19 June 2024

Tax status	Expired at 15 March 2024
Days left	46 days too late
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2004-09-29
Last registration	2023-06-07
Complete history	See info



Registration #1	2004-09-29	8 mi
Registration #2	2007-09-26	17.709 mi
Registration #3	2008-09-18	27.744 mi
Registration #4	2009-09-29	33.616 mi
Registration #5	2010-09-28	38.367 mi
Registration #6	2011-10-12	43.492 mi
Registration #7	2011-11-25	43.511 mi
Registration #8	2012-11-02	64.141 mi
Registration #9	2013-06-20	75.857 mi
Registration #10	2014-06-10	78.718 mi
Registration #11	2015-06-15	80.397 mi
Registration #12	2015-06-19	80.445 mi
Registration #13	2016-06-15	83.819 mi
Registration #14	2016-06-20	83.820 mi
Registration #15	2017-05-25	86.351 mi
Registration #16	2018-05-25	91.377 mi
Registration #17	2019-05-25	96.403 mi
Registration #18	2020-05-25	101.429 mi
Registration #19	2021-05-25	106.455 mi
Registration #20	2022-05-25	111.481 mi
Registration #21	2023-05-25	116.507 mi
Registration #22	2024-05-25	121.533 mi
Registration #23	2025-05-25	126.559 mi
Registration #24	2026-05-25	131.585 mi
Registration #25	2027-05-25	136.611 mi
Registration #26	2028-05-25	141.637 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2

