





report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T3
Colour	Grey
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	72.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	72.4 mpg
CO2 emission	89 g/km
CO2 label	Α



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2025-01-15
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	19
Total items failed	11
MOT #23	2024-01-16 12:32
MOT #23 MOT test number	2024-01-16 12:32 439668403326
MOT test number	439668403326
MOT test number Result	439668403326 ✓ Passed
MOT test number Result	439668403326 ✓ Passed
MOT test number Result Next expiry date	439668403326 ✓ Passed 2025-01-15

MOT #21	2023-01-19 12:07
MOT test number	916833953199
Result	✓ Passed

MOT #20	2022-07-21 11:44
MOT test number	795140382535
Result	✓ Passed

CarCheck.co.uk page 2/13



MOT #19 2022-07-21 11:12

MOT test number 507614085525

Result X Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18 2022-01-17 14:58

MOT test number 378960051399

MOT #17 2021-07-22 12:50

MOT test number 369024995777

MOT #16 2021-01-22 12:17

MOT test number 416511164588

Result ✓ Passed

MOT #15 2020-01-08 15:39

MOT test number 568813385667

Result

Passed

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

(b))

CarCheck.co.uk page 3/13



MOT #14 2020-01-08 15:39

MOT test number 577843469443

Result X Failed

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Pass with rectification

all lamps (4.7.1 (b) (ii))

Nearside Rear Registration plate lamp inoperative in the case of a single lamp or

MOT #13 2019-06-29 11:31

MOT test number 787724064733

Result ✓ Passed

MOT #12 2018-12-31 15:20

MOT test number 678593197687

Result ✓ Passed

MOT #11 2018-12-31 15:20

MOT test number 763972250711

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

MOT #10 2018-07-04 16:43

MOT test number 914769556873

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9 2018-06-21 17:14

MOT test number 621663910565

Result Passed

Advice Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

MOT #8 2018-06-21 09:38

MOT test number 230670088361

Result X Failed

Fail

Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #7 2017-12-21 12:51

MOT test number 941630946785

Advice Front Brake pad(s) wearing thin Both sides (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened Both sides (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/13



Result

LP14AEW

report date: 2024-03-29

✓ Passed

MOT #6		2017-12-21 12:51
MOT test number		154065238486
Result		× Failed
Advice Nearside Front	Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Sh	ock absorber has a light misting of oil (2.7.3)	
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Front Brake pad	(s) wearing thin Both sides (3.5.1g)	
Advice Offside Front Ty	re worn close to the legal limit (4.1.E.1)	
Advice Front brake disc	worn, pitted or scored, but not seriously weakened Both sig	des (3.5.1i)

Advice Front brake disc worn, pitted or scored, but not seriously weakened Both sides (3.5.1i)		
MOT #5		2017-06-23 14:26
MOT test	number	337706449571
Result		✓ Passed
MOT #4		2016-12-23 15:25
MOT test	number	656818866923
Result		✓ Passed
MOT #3		2016-06-29 12:30
MOT test	number	623166251527
Result		✓ Passed
MOT #2		2016-01-04 10:12
MOT test	number	576396278838
Result		✓ Passed
MOT #1		2015-07-02 18:44
MOT test	number	868383585185

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	استحاجاتا
Owner	nistory
OVVIICI	IIIJCOI 9

, , , , , , , , , , , , , , , , , , , ,		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it		OTA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	NK NK	
Flate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2014-06-30
Last registration	2024-01-16
Complete history	See info



Registration #1	2014-06-30	8 mi
Registration #2	2015-07-02	35.874 mi
Registration #3	2016-01-04	56.024 mi
Registration #4	2016-06-29	78.136 mi
Registration #5	2016-12-23	96.381 mi
Registration #6	2017-06-23	112.140 mi
Registration #7	2017-12-21	126.853 mi
Registration #8	2017-12-21	126.853 mi
Registration #9	2018-06-21	141.812 mi
Registration #10	2018-06-21	141.812 mi
Registration #11	2018-07-04	142.756 mi
Registration #12	2018-12-31	164.416 mi
Registration #13		11.777 esi
Registration #14		11.777 es
Registration #15		11.777 esi
Registration #16		11.777 es
Registration #17		11.777 esi
Registration #18		11.777 es
Registration #19		11.777 esi
Registration #20		11.777 es
Registration #21		11,777 es
Registration #22		11.777 es
Registration #23		11,777 es
Registration #24		77.777 au

More info >



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1425 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1.

Engine number

2ZRU870525