



General information

Make	FORD
Model	FUSION ZETEC
Colour	Black
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2

Date	2022-02-10
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2022-01-13
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-03
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	26
Total items failed	4

MOT #15	2024-02-29 15:57
MOT test number	841519674971
Result	✓ Passed
Next expiry date	2025-03-03
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2024-02-29 15:31
MOT test number	578453106971
Result	✗ Failed
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2023-02-21 10:38

MOT test number

617298147289

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear condensation in lamp unit**Advice** High level brake light inoperative**MOT #12**

2023-02-21 10:00

MOT test number

167108807512

Result

✗ Failed

Advice Offside Rear condensation in lamp unit**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** High level brake light inoperative**MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #11**

2022-03-04 16:09

MOT test number

961922535462

Result

✓ Passed

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge and starting to crack (5.2.3 (e))

**MOT #10** 2021-09-15 11:04**MOT test number** 816712425031**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #9** 2020-09-25 13:52**MOT test number** 568050398404**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2019-09-26 11:29**MOT test number** 543055475778**Result** ✓ Passed**MOT #7** 2018-10-02 09:09**MOT test number** 805705745791**Result** ✓ Passed**MOT #6** 2017-11-01 14:34**MOT test number** 621799763794**Result** ✓ Passed

**MOT #5** 2017-10-27 10:52**MOT test number** 527489891719**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)

MOT #4 2016-10-14 09:54**MOT test number** 570151057885**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2015-10-09 08:51**MOT test number** 836657624085**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 195/60/15 (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-10-02 09:57**MOT test number** 487635274237**Result** ✓ Passed**MOT #1** 2013-08-09 14:56**MOT test number** 916281523267**Result** ✓ Passed

- Notice** Nail in offside front tyre



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	WU60NCC
Plate since	2024-03-28
Current registration	WU60NCC
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-03
Last registration	2024-02-29
Complete history	See info



Registration #1	2010-09-03	11 mi
Registration #2	2013-08-09	11.430 mi
Registration #3	2014-10-02	19.399 mi
Registration #4	2015-10-09	25.764 mi
Registration #5	2016-10-14	31.710 mi
Registration #6	2017-10-27	38.714 mi
Registration #7	2017-11-01	38.796 mi
Registration #8	2018-10-02	43.960 mi
Registration #9	2019-09-26	49.947 mi
Registration #10	2020-09-26	55.934 mi
Registration #11	2021-09-26	61.921 mi
Registration #12	2022-09-26	67.908 mi
Registration #13	2023-09-26	73.895 mi
Registration #14	2024-02-29	79.882 mi
Registration #15	2024-02-29	79.882 mi
Registration #16	2024-02-29	79.882 mi
Registration #17	2024-02-29	79.882 mi
Registration #18	2024-02-29	79.882 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AP59922