




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2012
Top speed	133 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	120 g/km
CO2 label	C







Internet history

Entry 2

Date	2023-02-03
Pictures	21
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-27
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-06
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #12	2024-02-02 11:50
MOT test number	248741358910
Result	✓ Passed
Next expiry date	2025-02-06
Advice	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2023-01-23 08:39
MOT test number	152085825868
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly worn on inner edge of tread
Minor	Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bonded bush slightly worn/perished (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bonded bush slightly worn/perished (5.3.4 (a) (i))

**MOT #10**

2023-01-23 08:39

**MOT test number**

477729358804

**Result****✗ Failed****Pass with rectification** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bonded bush slightly worn/perished (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly worn on inner edge of tread**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bonded bush slightly worn/perished (5.3.4 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9**

2022-02-07 15:00

**MOT test number**

536547938134

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2020-10-28 16:23

**MOT test number**

955628225231

**Result****✓ Passed****MOT #7**

2019-10-28 12:18

**MOT test number**

437529422745

**Result****✓ Passed**

**MOT #6** 2018-10-25 10:33**MOT test number** 387556838623**Result** ✓ Passed**MOT #5** 2017-09-28 12:35**MOT test number** 500856400693**Result** ✓ Passed**MOT #4** 2017-09-28 09:13**MOT test number** 175796468155**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #3** 2016-09-29 08:36**MOT test number** 472083600363**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-09-30 13:50**MOT test number** 808965369426**Result** ✓ Passed**MOT #1** 2015-09-30 10:15**MOT test number** 165155389814**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
6 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	6 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>PE62EWG</b>
Plate since	2024-03-29
Current registration	 <b>PE62EWG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-28
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2012-09-28	26 mi
Registration #2	2015-09-30	17.571 mi
Registration #3	2015-09-30	17.571 mi
Registration #4	2016-09-29	25.896 mi
Registration #5	2017-09-28	38.910 mi
Registration #6	2017-09-28	38.919 mi
Registration #7	2018-10-25	53.452 mi
Registration #8	2019-10-28	66.281 mi
Registration #9	2020-05-20	75.277 mi
Registration #10	2020-05-20	75.277 mi
Registration #11	2020-05-20	75.277 mi
Registration #12	2020-05-20	75.277 mi
Registration #13	2020-05-20	75.277 mi
Registration #14	2020-05-20	75.277 mi
Registration #15	2020-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1550 kg
Max. allowed weight	2050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFFBD24555