



BN60DDZ

report date: 2024-03-29

General information

Make	FORD
Model	FIESTA EDGE
Colour	Black
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #152024-03-06 13:54

MOT test number515182552235

Result✓ Passed

Next expiry date2025-03-05

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #142024-03-06 11:33

MOT test number626886712532

Result✗ Failed

Fail Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp aim unable to be tested (4.1.2 (b))

MOT #132023-03-20 11:49

MOT test number299917214053

Result✓ Passed

**MOT #12** 2022-04-05 14:25**MOT test number** 463947971262**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-04-12 12:19**MOT test number** 453142291663**Result** ✓ Passed**MOT #10** 2020-01-04 13:29**MOT test number** 643242614574**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside (1.1.14 (a) (ii))**MOT #9** 2019-01-24 14:02**MOT test number** 753234155610**Result** ✓ Passed**MOT #8** 2019-01-23 11:08**MOT test number** 759438699220**Result** ✗ Failed**Fail** Nearside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #7** 2018-10-04 09:24**MOT test number** 328915743363**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #6 2018-10-03 15:05**MOT test number** 374397657151**Result** ✗ Failed

- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #5 2017-09-23 08:19**MOT test number** 297294399758**Result** ✓ Passed

**MOT #4** 2016-09-30 14:27**MOT test number** 189644721228**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement axle bush (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement axle bush (2.4.G.2)**MOT #3** 2015-09-25 12:18**MOT test number** 185227402463**Result** ✓ Passed**MOT #2** 2014-10-04 09:43**MOT test number** 866457474294**Result** ✓ Passed**MOT #1** 2013-09-27 09:34**MOT test number** 345940473209**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
5 March 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BN60DDZ
Plate since	2019-09-29
Current registration	BN60DDZ
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-30
Last registration	2024-03-06
Complete history	See info



Registration #1	2010-09-30	20 mi
Registration #2	2013-09-27	24.216 mi
Registration #3	2014-10-04	32.247 mi
Registration #4	2015-09-25	39.857 mi
Registration #5	2016-09-30	44.580 mi
Registration #6	2017-09-23	49.166 mi
Registration #7	2018-10-03	50.696 mi
Registration #8	2018-10-04	50.696 mi
Registration #9	2019-01-23	50.725 mi
Registration #10	2019-01-23	50.725 mi
Registration #11	2019-01-23	50.725 mi
Registration #12	2019-01-23	50.725 mi
Registration #13	2019-01-23	50.725 mi
Registration #14	2019-01-23	50.725 mi
Registration #15	2019-01-23	50.725 mi
Registration #16	2019-01-23	50.725 mi
Registration #17	2019-01-23	50.725 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	AU64848