



report date: 2024-03-28

General information

Make	MAZDA
Model	5 D SPORT NAV
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2021-12-08
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	51
Total items failed	12

MOT #15	2020-12-09 16:10
MOT test number	646518094072
Result	✓ Passed
Next expiry date	2021-12-08
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #14	2019-12-03 12:18
MOT test number	152029738041
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))



MOT #13

2019-03-13 08:57

MOT test number

697425142194

Result

✓ Passed

- Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2019-03-12 09:24

**MOT test number**

527917002777

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**MOT #11**

2018-03-20 10:23

**MOT test number**

570856910618

**Result****✓ Passed**

- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit inner edge bald (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' stone chip (8.3.1a)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides lipped\corroded (3.5.1i)

**MOT #10**

2018-03-19 09:53

**MOT test number**

229708363895

**Result****✗ Failed****Fail** Offside Headlamp aim not tested (1.8.A.1c)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides lipped\corroded (3.5.1i)**Fail** Offside Rear Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front suspension has excessive play in a track control arm inner bush rear bush excessively worn (2.5.B.2b)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' stone chip (8.3.1a)**Advice** Offside Rear Tyre worn close to the legal limit inner edge bald (4.1.E.1)**MOT #9**

2017-03-24 09:13

**MOT test number**

307048905482

**Result****✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear heat shield loose

**MOT #8** 2017-03-11 13:28**MOT test number** 345881548383**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear heat shield loose**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-03-23 16:48**MOT test number** 329213448613**Result** ✓ Passed**Advice** Tyre worn close to the legal limit all four tyres worn badly on inner and outer edges. (4.1.E.1)**MOT #6** 2016-03-18 10:33**MOT test number** 258407805094**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively both front. (8.2.2)**Advice** Tyre worn close to the legal limit all four tyres worn badly on inner and outer edges. (4.1.E.1)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush. (2.4.G.2)

**MOT #5** 2015-03-04 16:58**MOT test number** 596403865040**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-03-31 15:58**MOT test number** 705280894096**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-03-27 13:25**MOT test number** 805566284060**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Rear fog lamp not working (1.3.2b)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #2** 2013-03-07 09:49**MOT test number** 169826663050**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #12012-03-08 12:30

MOT test number925798162018

Result

✓ Passed

- Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice

Child seat fitted not allowing full inspection of adult belt





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-31
Last registration	2020-12-09
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	11 mi
Registration #2	2012-03-08	21.616 mi
Registration #3	2013-03-07	30.669 mi
Registration #4	2014-03-27	38.885 mi
Registration #5	2014-03-31	38.885 mi
Registration #6	2015-03-04	45.451 mi
Registration #7	2016-03-18	53.319 mi
Registration #8	2016-03-23	53.319 mi
Registration #9	2016-03-23	53.319 mi
Registration #10	2016-03-23	53.319 mi
Registration #11	2016-03-23	53.319 mi
Registration #12	2016-03-23	53.319 mi
Registration #13	2016-03-23	53.319 mi
Registration #14	2016-03-23	53.319 mi
Registration #15	2016-03-23	53.319 mi
Registration #16	2016-03-23	53.319 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1535 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	RF 10246627