



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMASTAR SE LWB 115DCI SHR P/V
Colour	Silver
Year of manufacture	2007
Top speed	160 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	46
Total items failed	23

MOT #20	2023-07-05 11:22
MOT test number	982416001522
Result	✓ Passed
Next expiry date	2024-07-04
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19	2023-07-05 11:22
MOT test number	423861955591
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #18**

2022-06-14 10:06

MOT test number

600177964462

Result

✓ Passed

- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #17

2022-06-14 10:06

MOT test number

740321902011

Result

✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #16** 2021-06-17 14:16**MOT test number** 140881954174**Result** ✓ Passed**MOT #15** 2018-09-03 15:33**MOT test number** 668759134869**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin Look low (1.1.13 (a) (ii))

MOT #14 2018-08-31 11:25**MOT test number** 742731828132**Result** ✗ Failed

- Fail** Offside Brake pipe excessively corroded Front to rear (1.1.11 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin Look low (1.1.13 (a) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

MOT #13 2017-08-07 15:23**MOT test number** 239596118390**Result** ✓ Passed

- Advice** Oil leak
- Advice** Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)

**MOT #12**

2017-08-07 11:02

MOT test number

954620798354

Result

✗ Failed

Advice Oil leak**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #11**

2016-08-22 14:51

MOT test number

687739321824

Result

✓ Passed

MOT #10

2016-08-22 08:44

MOT test number

870676849531

Result

✗ Failed

Fail Nearside Stop lamp not working (1.2.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**MOT #9**

2015-09-01 08:31

MOT test number

863898426099

Result

✓ Passed

MOT #8

2015-01-10 14:19

MOT test number

289590015094

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**Notice** Rear brake pipes have grease on them

**MOT #7** 2013-12-28 12:28**MOT test number** 316652263376**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Play in steering rack inner joint(s)**MOT #6** 2013-12-27 10:45**MOT test number** 329081663392**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #5** 2013-01-03 09:51**MOT test number** 657163403016**Result** ✓ Passed**Advice** Front front brake grabbing slightly (3.7.A.2b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2011-12-08 11:00**MOT test number** 438102141318**Result** ✓ Passed

**MOT #3** 2011-12-07 16:57**MOT test number** 876651641349**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Offside Rear Rear wheel bearing has excessive play (2.6.2)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Fail** Centre Stop lamp not working (1.2.1b)**MOT #2** 2010-12-03 14:16**MOT test number** 852587430352**Result** ✓ Passed**Advice** Offside Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #1** 2010-12-02 12:17**MOT test number** 501506530315**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear wheel bearing has slight play (2.6.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)



Tax & MOT check

✕
Untaxed

Tax expired:
3 March 2024

✓
MOT

Expires:
4 July 2024

Tax status

Expired at 3 March 2024

Days left

58 days too late

MOT expiry date

4 July 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-12-04
Last registration	2023-07-05
Complete history	See info



Registration #1	2007-12-04	25 mi
Registration #2	2010-12-02	52.890 mi
Registration #3	2010-12-03	52.898 mi
Registration #4	2011-12-07	58.434 mi
Registration #5	2011-12-08	58.434 mi
Registration #6	2013-01-03	63.508 mi
Registration #7	2013-12-27	69.341 mi
Registration #8	2013-12-28	69.349 mi
Registration #9	2015-01-10	74.268 mi
Registration #10	2015-09-01	78.112 mi
Registration #11	2016-08-22	88.218 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi
Registration #21	2019-05-20	95.377 mi
Registration #22	2019-05-20	95.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	156260