





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Black
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-11

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



KS58KKN report date: 2024-03-28

MOT history

MOT expiry date	2025-03-05
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #15	2024-03-01 10:13
MOT test number	785645367447
Result	✓ Passed
Next expiry date	2025-03-05
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #14	2023-03-03 14:17
MOT test number	229835426304
Result	✓ Passed

MOT #13	2022-02-26 11:30
MOT test number	826192238025
Result	✓ Passed

MOT #12	2022-02-26 08:51
MOT test number	944603605018
Result	× Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11		2021-03-03 15:48
MOT test i	number	933466972450
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inside ed	ge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracks in tread (5.2	.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inside edge	e (5.2.3 (e))

MOT #10	2020-02-28 09:45
MOT test number	987849001844
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #9	2019-03-05 10:51
MOT test number	314834105799
Result	✓ Passed
MOT #8	2018-03-06 10:56
MOT test number	900946760131
Result	✓ Passed
MOT #7	2017-08-18 08:26
MOT test number	107319159468
Result	✓ Passed

MOT #6	2016-08-22 08:13
MOT test number	523622486226
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2015-01-26 17:04

MOT test number 398206925013

Result ✓ Passed

MOT #4 2013-12-14 11:53

MOT test number 128028043301

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2013-12-14 11:53

MOT test number 145068443362

Result X Failed

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2012-12-21 10:38

MOT test number 506276852351

Result

Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1 2011-12-21 11:12

MOT test number 979365851397

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	
	More info >
Plate changes See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-30
Last registration	2024-03-01
Complete history	See info



Registration #1	2008-12-30	8 mi
Registration #2	2011-12-21	30.419 mi
Registration #3	2012-12-21	40.985 mi
Registration #4	2013-12-14	51.210 mi
Registration #5	2015-01-26	58.486 mi
Registration #6	2016-08-22	64.143 mi
Registration #7	2017-08-18	71.093 mi
Registration #8	2018-03-06	75.851 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.77 44
Registration #15		11.777 es
Registration #16		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CBA 056163