





report date: 2024-03-28

### General information

Make	KIA
Model	PICANTO X-LINE S
Colour	Green
Year of manufacture	2018
Top speed	107 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	82 BHP
Max. torque	121 Nm at 4.000 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	74.3 mpg
Consumption combined	61.4 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



HK18UDG
report date: 2024-03-28

## Internet history

### Entry 2

Date 2021-09-24

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

|--|

Pictures 51

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



HK18UDG report date: 2024-03-28

MOT history

MOT expiry date	2024-06-28
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #3		2023-06-17 09:05
MOT test	number	933743665419
Result		✓ Passed
Next expi	ry date	2024-06-28
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #2		2022-06-15 09:53
MOT test i	number	848257361886
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Brake pipe clips or supports missing, pipe adequately supported both front to re	ear (1.1.11 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-06-25 08:38

**MOT test number** 972900904356

**Result** ✓ Passed

CarCheck.co.uk page 4/11



HK18UDG
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	28 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

e mier metery	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-06-29
Last registration	2023-06-17
Complete history	See info



Registration #1	2018-06-29	21 mi
Registration #2	2021-06-25	14.941 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		0.77

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

## Safety ratings

NCAP rating	****
Adult	87%
Children	64%
Pedestrian	54%
Safety systems	47%
Overall rating	68%
Video	see crash video



## Dimensions & weight

Width	1625 mm
Height	3670 mm
Length	3670 mm
Wheel base	2400 mm
Kerb weight	1051 kg
Max. allowed weight	1400 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** G4LAJP038634