



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Black
Year of manufacture	2009
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F





MOT history

MOT expiry date	2025-02-20
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	47
Total items failed	22

MOT #19	2024-02-21 15:05
MOT test number	914625480834
Result	✓ Passed
Next expiry date	2025-02-20
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
Advice	Rear bump stops broken

**MOT #18**

2024-02-15 15:15

**MOT test number**

352336979137

**Result****✗ Failed**

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
- Advice** Unable to test rear wheel bearings due to excessive binds
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Rear bump stops broken
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Fail** Rear Brakes imbalanced across an axle nearside behind (1.2.1 (b) (i))



MOT #17

2023-02-18 09:41

MOT test number

679178272119

Result

✓ Passed

- Advice

Both rear bump stops broken
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge 2.5mm and very heavily worn inner edge (5.2.3 (e))
- Minor

Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm, has a nail in and is perished (5.2.3 (e))
- Minor

Rear Position lamp with a multiple light source up to 1/2 not functioning both (4.2.1 (a) (i))

**MOT #16**

2023-02-10 10:58

**MOT test number**

466479243388

**Result****✗ Failed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm, has a nail in and is perished (5.2.3 (e))

**Fail**

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail**

Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**Minor**

Rear Position lamp with a multiple light source up to 1/2 not functioning both (4.2.1 (a) (i))

**Advice**

Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

**Fail**

Nearside Side repeater not working (4.4.1 (a) (ii))

**Advice**

Both rear bump stops broken

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge 2.5mm and very heavily worn inner edge (5.2.3 (e))

**Fail**

Rear Brakes imbalanced across an axle nearside behind (1.2.1 (b) (i))

**Minor**

Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Fail**

Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Minor**

Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #15**

2022-01-28 09:11

**MOT test number**

233607822508

**Result****✓ Passed****Advice**

Offside Rear bump stop broken

**Minor**

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #14** 2021-02-12 14:15**MOT test number** 324383145272**Result** ✓ Passed**MOT #13** 2019-11-23 12:05**MOT test number** 357076247340**Result** ✓ Passed**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #12** 2019-11-22 11:02**MOT test number** 286738280853**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2018-12-06 16:00**MOT test number** 839917266740**Result** ✓ Passed

**MOT #10** 2018-12-06 16:00**MOT test number** 193404983113**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #9** 2017-12-13 14:57**MOT test number** 654784833916**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-12-13 09:51**MOT test number** 514979767980**Result** ✗ Failed**Fail** Rear brake excessively fluctuating (3.7.B.3)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Nearside Brake cable has restricted free movement (3.5.1k)**Fail** Rear brake application uneven (3.7.B.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-02-23 14:58**MOT test number** 709585827034**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear tyre perished

**MOT #6** 2017-02-23 10:03**MOT test number** 238165675621**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside rear brake binding (3.7.B.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear tyre perished**Fail** Offside rear brake binding (3.7.B.1)**MOT #5** 2016-02-16 12:19**MOT test number** 135751373209**Result** ✓ Passed**MOT #4** 2015-02-27 09:40**MOT test number** 846468955014**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre worn feathered**MOT #3** 2013-11-04 13:25**MOT test number** 908778403356**Result** ✓ Passed**MOT #2** 2013-11-04 10:53**MOT test number** 949138303390**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (1.4.A.2c)





MOT #1	2012-10-17 15:12
MOT test number	559951592235
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	20 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VK59AZT</b>
Plate since	2019-06-29
Current registration	 <b>VK59AZT</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-23
Last registration	2024-02-21
Complete history	<a href="#">See info</a>



Registration #1	2009-09-23	24 mi
Registration #2	2012-10-17	31.331 mi
Registration #3	2013-11-04	38.359 mi
Registration #4	2013-11-04	38.359 mi
Registration #5	2015-02-27	46.116 mi
Registration #6	2016-02-16	51.132 mi
Registration #7	2017-02-23	58.204 mi
Registration #8	2017-02-23	58.204 mi
Registration #9	2017-12-13	64.104 mi
Registration #10	2017-12-13	64.104 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1199 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3



Number of seats	5
Number of axles	2
Engine number	BUD 477184