



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 R-DESIGN EDITION
Colour	Blue
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.2 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-08-11
Pictures	19
Listing price	<a href="#">View report</a>

**AA**

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #13	2023-09-01 09:08
MOT test number	966461955030
Result	✓ Passed
Next expiry date	2024-08-31

MOT #12	2022-08-16 16:00
MOT test number	177121828126
Result	✓ Passed

MOT #11	2022-08-12 09:18
MOT test number	775879586576
Result	✗ Failed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10	2021-07-29 10:02
MOT test number	616976125168
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2020-08-05 11:43**MOT test number** 753924521336**Result** ✓ Passed**MOT #8** 2019-05-28 15:04**MOT test number** 889936880904**Result** ✓ Passed**MOT #7** 2019-05-28 08:10**MOT test number** 714385030766**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords age cracks (5.2.3 (d) (i))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords age cracks (5.2.3 (d) (i))**MOT #6** 2018-06-01 08:32**MOT test number** 772123728791**Result** ✓ Passed**MOT #5** 2018-05-31 07:47**MOT test number** 249226523591**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))



<b>MOT #4</b>	2017-05-26 11:44
---------------	------------------

<b>MOT test number</b>	275612933682
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2016-05-11 09:54
---------------	------------------

<b>MOT test number</b>	280164544905
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Outer tyre wall cracked slightly.
---------------	--

<b>Advice</b>	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
---------------	--

<b>MOT #2</b>	2015-05-12 10:46
---------------	------------------

<b>MOT test number</b>	927762335165
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
---------------	--

<b>MOT #1</b>	2014-05-27 10:27
---------------	------------------

<b>MOT test number</b>	526517644107
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-25
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2011-05-25	15 mi
Registration #2	2014-05-27	4.788 mi
Registration #3	2015-05-12	7.260 mi
Registration #4	2016-05-11	8.526 mi
Registration #5	2017-05-26	12.065 mi
Registration #6	2018-05-31	27.656 mi
Registration #7	2018-06-01	27.656 mi
Registration #8	2019-05-28	40.658 mi
Registration #9	2019-05-28	40.658 mi
Registration #10	2019-05-28	40.658 mi
Registration #11	2019-05-28	40.658 mi
Registration #12	2019-05-28	40.658 mi
Registration #13	2019-05-28	40.658 mi
Registration #14	2019-05-28	40.658 mi
Registration #15	2019-05-28	40.658 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1379 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1045425