





report date: 2024-03-28

General information

Make	FIAT
Model	TIPO MULTIJET EASY PLUS
Colour	Red
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



WN17KKP
report date: 2024-03-28

Internet history

-		-		1
п	L	ΓV	,	т.

EIIII y I	
Date	2021-08-24
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



WN17KKP
report date: 2024-03-28

MOT history

MOT expiry date	2024-07-15
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	8

MOT #7	2023-07-14 16:00
MOT test number	269558133950
Result	✓ Passed
Next expiry date	2024-07-15
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #6	2023-07-14 11:32
MOT test number	667670657309
Result	X Failed
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Nearside Direction indicator not working Repeater (4.4.1 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

301694679137

MOT #5 2023-07-07 10:19

MOT test number 423445282255

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Rear Nail in tyre

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Under body covers fitted

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front tyres excess worn edges

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear brake calliper fault/lever on stop with brake on

MOT #4 2022-07-08 08:49

Result ✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm&perished-advise new-225/45/17

(5.2.3(e))

MOT test number

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2021-07-16 15:13 **MOT test number** 835871103620 ✓ Passed Result MOT #2 2020-11-11 17:29 123126203129 **MOT test number** Result ✓ Passed MOT #1 2020-05-10 09:35 **MOT test number** 136028169376 Result ✓ Passed **Advice COVID-19 6 MONTH EXTENSION**

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	15 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-18
Last registration	2023-07-14
Complete history	See info



Registration #1	2017-05-18	18 mi
Registration #2	2020-11-11	22.070 mi
Registration #3	2021-07-16	24.331 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1370 kg
Max. allowed weight	1795 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number 7973051