



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T2
Colour	Red
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #16	2021-01-15 18:03
MOT test number	950376121059
Result	✓ Passed
Next expiry date	2022-01-14
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pipe corroded, covered in grease or other material offside & nearside (1.1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2019-06-29 14:07
MOT test number	170679408369
Result	✓ Passed
Advice	Offside Front Macpherson strut mounting damaged but not seriously weakened shocker top mount (5.3.3 (b) (i))

MOT #14	2018-06-22 15:47
MOT test number	376698201509
Result	✓ Passed

MOT #13	2017-07-04 15:25
MOT test number	616842346826
Result	✓ Passed
Advice	Nearside Front Outer Tyre worn close to the legal limit edges (4.1.E.1)
Advice	Offside Front Outer Tyre worn close to the legal limit edges (4.1.E.1)
Advice	Clean dirt around the windscreen base.

**MOT #12**

2016-07-26 12:24

MOT test number

294492777142

Result

✓ Passed

Advice Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Brake pipe slightly corroded to rear (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2016-07-26 09:41

MOT test number

896454652821

Result

✗ Failed

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside mirror insecure**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Brake pipe slightly corroded to rear (3.6.B.2c)**Advice** Oil level at minimum**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #10** 2015-07-23 10:15**MOT test number** 397994905434**Result** ✓ Passed**MOT #9** 2014-07-22 18:19**MOT test number** 217533404223**Result** ✓ Passed**MOT #8** 2014-07-22 15:46**MOT test number** 468443304206**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2013-07-26 10:31**MOT test number** 318647103401**Result** ✓ Passed**Notice** 3rd row seats stowed unable to check seat belts**MOT #6** 2013-07-26 10:31**MOT test number** 658777803292**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Notice** 3rd row seats stowed unable to check seat belts**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

**MOT #5** 2012-07-18 14:46**MOT test number** 336670402216**Result** ✓ Passed**MOT #4** 2011-07-21 16:51**MOT test number** 666992801241**Result** ✓ Passed**MOT #3** 2010-08-12 10:09**MOT test number** 942404420249**Result** ✓ Passed**Notice** Slight cut too o/s/f tyre**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-08-12 10:09**MOT test number** 842004920249**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Slight cut too o/s/f tyre**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2009-08-12 15:31**MOT test number** 502234829296**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-10-30
Last registration	2021-01-15
Complete history	See info



Registration #1	2006-10-30	18 mi
Registration #2	2009-08-12	31.946 mi
Registration #3	2010-08-12	48.672 mi
Registration #4	2011-07-21	61.679 mi
Registration #5	2012-07-18	75.167 mi
Registration #6	2013-07-26	87.453 mi
Registration #7	2014-07-22	101.364 mi
Registration #8	2014-07-22	101.364 mi
Registration #9	2015-05-20	115.377 mi
Registration #10	2016-05-20	129.390 mi
Registration #11	2017-05-20	143.403 mi
Registration #12	2018-05-20	157.416 mi
Registration #13	2019-05-20	171.429 mi
Registration #14	2020-05-20	185.442 mi
Registration #15	2021-05-20	199.455 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	3ZZE456372