





report date: 2024-03-28

#### General information

Make	MERCEDES
Model	CL 500 500
Colour	Black
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	382 BHP
Max. torque	530 Nm at 2.800 rpm
Engine capacity	5.461 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.6 mpg
Consumption extra urban	33.2 mpg
Consumption combined	23.3 mpg
CO2 emission	288 g/km
CO2 label	М



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

#### Entry 1

Date	2021-06-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$			
10.71	$\alpha$	- h	sto	rv
101	( ) I		510	II V
	•		-	. ,

MOT expiry date	2023-09-23
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	11
Total items failed	3

MOT #12	2022-08-31 14:38
MOT test number	401523902662
Result	<b>✓</b> Passed
Next expiry date	2023-09-23

MOT #11	2021-09-24 11:43
MOT test number	494420653065
Result	✓ Passed

MOT #10	2021-09-24 11:43	
MOT test number	250522644509	
Result	<b>▼</b> Failed	
Pass with rectification	Road wheel more than one fixing missing 1 bolt on all 4 wheels (5.2.1 (a) (ii))	
Pass with rectification	tification Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #9	2020-07-28 16:56
MOT test number	414534837795
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

861348841546

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Advice Engine covers and Under-trays fitted obscuring some underside components

**MOT #7** 2018-07-16 11:55 **MOT** test number 211123946559 Result ✓ Passed **MOT #6** 2017-07-25 10:14 **MOT** test number 635074362828 Result ✓ Passed **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Engine and under tray covers fitted restricted view **Advice** Rear Brake pad(s) wearing thin (3.5.1g) Advice Oil leak oil on under tray Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5		2016-07-27 09:47
MOT test	number	486132434632
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #4	2015-07-22 11:22
MOT test number	876533105293
Result	<b>✓</b> Passed
MOT #3	2014-07-29 13:08
MOT test number	879310914220
Result	✓ Passed
MOT #2	2013-09-14 12:28
MOT test number	555927753215
Result	<b>✓</b> Passed
MOT #1	2012-09-29 11:56
MOT test number	317413272248
Result	✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.


#### Damage 1

**Date Category Type** Damage 2

Category

**Type** 

**Date** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

Owner History	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo here.	
2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
*********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-09-30
Last registration	2022-08-31
Complete history	See info



Registration #1	2009-09-30	28 mi
Registration #2	2012-09-29	31.675 mi
Registration #3	2013-09-14	36.845 mi
Registration #4	2014-07-29	43.852 mi
Registration #5	2015-07-22	51.548 mi
Registration #6	2016-07-27	89.753 mi
Registration #7	2017-07-25	66.614 mi
Registration #8		11.777 es
Registration #9		0.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		0.00 44
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1871 mm
Height	1418 mm
Length	5065 mm
Wheel base	2955 mm
Kerb weight	1995 kg

## Additional information

Fuel tank capacity	90 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27396130298262

CarCheck.co.uk page 11/11