



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Beige
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-17
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #18	2021-11-03 07:39
MOT test number	752526139743
Result	✓ Passed
Next expiry date	2022-11-02
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
<b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))	
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
<b>Advice</b> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17	2021-11-03 07:39
MOT test number	338892233100
Result	✗ Failed
<b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))	
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
<b>Advice</b> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Pass with rectification</b> Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	

MOT #16	2020-09-14 14:28
MOT test number	247107843345
Result	✓ Passed

MOT #15	2020-03-11 10:44
MOT test number	868581916176
Result	✓ Passed

MOT #14	2019-03-06 10:57
MOT test number	539178355075
Result	✓ Passed



**MOT #13** 2018-03-13 11:36**MOT test number** 716371372960**Result** ✓ Passed**MOT #12** 2017-03-08 11:14**MOT test number** 477721405038**Result** ✓ Passed**MOT #11** 2016-03-19 13:16**MOT test number** 743321714316**Result** ✓ Passed**MOT #10** 2015-05-21 17:55**MOT test number** 217381045117**Result** ✓ Passed**MOT #9** 2015-05-21 16:27**MOT test number** 298461745455**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2014-06-07 13:26**MOT test number** 148788954178**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2014-06-06 16:34

**MOT test number**

896067154110

**Result****✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #6**

2013-06-06 10:41

**MOT test number**

608817253192

**Result****✓ Passed****Notice** Advise n/s/r light unit damaged**Notice** Advise rear exhaust box bracket corroded**Notice** Passenger seat(s) missing at time of test**Notice** Advise o/s/r tyre side wall cracking**MOT #5**

2012-06-06 12:08

**MOT test number**

279188552173

**Result****✓ Passed****MOT #4**

2012-03-28 16:24

**MOT test number**

779648182088

**Result****✓ Passed****Notice** Both rear tyre side walls starting to perish & crack



MOT #3	2011-04-04 11:41
MOT test number	886684191014
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-03-31 10:26
MOT test number	744090390071
Result	✓ Passed

MOT #1	2009-03-30 10:48
MOT test number	323239989040
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>WV06URW</b>
Plate since	2019-09-29
Current registration	<b>WV06URW</b>
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-29
Last registration	2021-11-03
Complete history	<a href="#">See info</a>



Registration #1	2006-03-29	15 mi
Registration #2	2009-03-30	20.024 mi
Registration #3	2010-03-31	25.833 mi
Registration #4	2011-04-04	30.713 mi
Registration #5	2012-03-28	35.173 mi
Registration #6	2012-06-06	35.987 mi
Registration #7	2013-06-06	44.074 mi
Registration #8	2014-06-06	52.644 mi
Registration #9	2014-06-07	52.644 mi
Registration #10	2015-05-21	57.894 mi
Registration #11	2016-05-21	58.277 mi
Registration #12	2017-05-21	58.277 mi
Registration #13	2018-05-21	58.277 mi
Registration #14	2019-05-21	58.277 mi
Registration #15	2020-05-21	58.277 mi
Registration #16	2021-05-21	58.277 mi
Registration #17	2022-05-21	58.277 mi
Registration #18	2023-05-21	58.277 mi
Registration #19	2024-05-21	58.277 mi
Registration #20	2025-05-21	58.277 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3097262