






report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27DCI 100 SWB P/V
Colour	Green
Year of manufacture	2002
Top speed	97 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	200 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.2 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-28


Internet history

Entry 1


Date 2021-10-16

Pictures 35

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



PLO2CMX report date: 2024-03-28

MOT history

MOT expiry date	2023-04-12
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	22
Total items failed	19

MOT #21		2022-04-13 13:23
MOT test	number	221632927981
Result		✓ Passed
Next expi	ry date	2023-04-12
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both	(1.1.14 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Rear revers light inop	

MOT #20		2022-04-13 08:59
MOT test	number	205934231139
Result		× Failed
DANGER detachmen	OUS Nearside Front Track rod end ball joint worn to the extent there is ant (2.1.3 (b) (ii))	a serious risk of
MAJOR	Front Windscreen washer not working (3.5 (a))	
MAJOR	Offside Rear Direction indicator adversely affected by the operation of an	other lamp (4.4.3 (b))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both ((1.1.14 (a) (ii))
MAJOR	Rear Registration plate lamp inoperative in the case of a single lamp or a	ll lamps (4.7.1 (b) (ii))
Advice	Rear revers light inop	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #19 2021-01-30 10:04

MOT test number 814902646390

MOT #18 2020-01-23 16:57

MOT test number 210667335333

Result
✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #17 2019-01-28 17:39

MOT test number 950761493150

Result \rightarrow Passed

MOT #16 2019-01-28 17:39

MOT test number 512752318620

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Pass with rectification Nearside Front Windscreen wiper blade missing (3.4 (b) (ii))

MOT #15 2018-02-02 16:36

MOT test number 581233528672

Result
✓ Passed

Advice Nearside Rear slight cracking starting within tread

Advice Offside Front Tyre worn close to the legal limit worn on both edages (4.1.E.1)

Advice Front both head lamps slightly discoloured

Advice Offside Rear slight cracking starting within tread

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #14 2017-01-24 13:12

MOT test number 704498440851

Result
✓ Passed

MOT #13 2016-02-04 18:12

MOT test number 745179040669

Result Passed

Advice Nearside Track rod end ball joint has slight play (2.2.B.1f)

MOT #12 2012-05-16 15:32

MOT test number 466627332122

Result ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #11 2012-05-16 15:32

MOT test number 248997332100

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Child seat fitted not allowing full inspection of adult belt

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10 2011-05-12 10:29

MOT test number 235922231427

Notice Child seat fitted not allowing full inspection of adult belt

Notice N/s/f suspension lower ball joint worn to limit.

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9 2010-05-04 14:31

MOT test number 420854420139

Result ✓ Passed

MOT #8 2010-05-04 14:31

MOT test number 732244520182

Result × Failed

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #7 2009-05-07 15:25

MOT test number 291767629184

Result \rightarrow Passed

MOT #6 2009-05-06 14:36

MOT test number 250056229151

Result X Failed

Fail Offside Body has a sharp edge caused by damage (6.1.C.1)

Fail Nearside Towbar component insecure (6.6.1)

Fail Rear Registration plate lamp not working (1.1.5c)

Fail Offside Front Macpherson strut has excessive movement in the upper support bearing assembly

(2.5.B.1b)

MOT #5 2008-05-02 15:50

MOT test number 220363228440

Result \rightarrow Passed

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

CarCheck.co.uk page 6/14



MOT #2

PL02CMX

report date: 2024-03-28

2006-04-19 12:36

MOT #	4	2007-04-27 11:12
MOT te	est number	681597417101
Result		✓ Passed
MOT #	3	2007-04-26 11:28
MOT te	est number	904856917146
Result		× Failed
Fail	Offside Front Lower Front suspension has excessive play in a lower suspension bal	l joint (2.5.B.1a)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail	Nearside Front Lower Front suspension has excessive play in a lower suspension b	all joint (2.5.B.1a)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT test number	323379406115
Result	✓ Passed
MOT #1	2006-04-19 12:36
MOT test number	822509806107
Result	★ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively
(8.2.2)	

CarCheck.co.uk page 7/14



PLO2CMX report date: 2024-03-28

Tax & MOT check



X MOT

Expired: 12 April 2023

Tax status Expired at 25 July 2022

Days left 645 days too late

MOT expiry date 12 April 2023

Full MOT history See MOT history

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

Plate changes	More info >
See in this check if this RENAULT had different number plates.	
Number of plates	
Number of plates Correct registration	JK UK
Number of plates Current registration Plate since	SIP. UK
Number of plates Current registration Fate since Current registration	IK UK

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-05-14
Last registration	2022-04-13
Complete history	See info



Registration #1	2002-05-14	20 mi
Registration #2	2006-04-19	44.986 mi
Registration #3	2007-04-26	56.154 mi
Registration #4	2007-04-27	56.154 mi
Registration #5	2008-05-02	65.673 mi
Registration #6	2009-05-06	73.980 mi
Registration #7	2009-05-07	73.991 mi
Registration #8	2010-05-04	83.517 mi
Registration #9	2011-05-12	90.924 mi
Registration #10	2012-05-16	99.072 mi
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 13/14



PLO2CMX report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

- C		_		
- I)ım	ension	SW	weiat	٦t
	ווטוכוום	3 UX	WEIGH	

Width	2232 mm
Length	4782 mm
Kerb weight	1677 kg
Max. allowed weight	2700 kg

Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	C018209

CarCheck.co.uk page 14/14