





report date: 2024-03-28

General information

Make	PEUGEOT
Model	HORIZON BLUE HDI S/S TEPEE ALLURE
Colour	Blue
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-01

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history


MOT expiry date	2024-10-06
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #7		2023-10-04 11:54
MOT test	number	741737723193
Result		✓ Passed
Next exp	ry date	2024-10-06
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Coolant level low	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1
Advice	Nearside and central rear seats removed	

CarCheck.co.uk page 3/12



report date: 2024-03-28



MOT #5	2022-10-07 13:41
MOT test number	328039885086
Result	✓ Passed
Advice Rear coil springs corroded	

MOT #4	2022-10-04 11:07
MOT test number	659442040512
Result	X Failed
Advice Rear coil springs corroded Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no of dirt (6.1.7 (g) (ii))	longer prevents the ingress

CarCheck.co.uk page 4/12



SF16FBB report date: 2024-03-28

MOT #3	2021-10-05 16:41
MOT test number	848742541302
Result	✓ Passed
MOT #2	2021-01-27 11:54
MOT test number	234092994981
Result	✓ Passed
MOT #1	2019-07-04 10:02
MOT test number	713859130908
Result	✓ Passed

CarCheck.co.uk page 5/12



SF16FBB report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



SF16FBB report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-07-13
Last registration	2023-10-04
Complete history	See info



Registration #1	2016-07-13	13 mi
Registration #2	2019-07-04	5.701 mi
Registration #3	2021-01-27	8.066 mi
Registration #4		11.777 es
Registration #5	2021-10-05	9.343 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	53
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

JBHB3076096